

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

YN 5744J
OD/Sompo

M/S: SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555 FAX: 62213302
ATTN: Motor Claim Department

Claim No: ES2290577

Date: 10 Jun 2022
Policy No: D21MTPCVE001791
Veh Reg No: YN5744J
Make/Model: MITSUBISHI MIT.
CANTER
FEB21ER3SDEB
Chassis No: FEB21EA00702
Engine No: 4P10B30337
Reg. Date: 31/07/2014

WS Ref: OD/SOMPO
Claim Type: Own Damage
Accident Date: 01/06/2022

NOT Notified
11 Rm &
Patching After Paint
12 days

Estimate Repair Cost to Vehicle No : YN5744J

Description	U/Price	Quantity	Cost SS	Amount SS
Cost Plus				
1 FRONT BUMPER	500.00	1 PC	500.00	✓
2 FRONT BUMPER RH BRACKET	110.00	1 PC	110.00	✓
3 FRONT BUMPER RH SIDE PAD	220.00	1 PC	220.00	✓
4 RH HEADLAMP	290.00	1 PC	290.00	✓
5 RH SIGNAL LAMP	170.00	1 PC	170.00	✓
6 RH HEADLAMP SIDE REFLECTOR	105.00	1 PC	105.00	✓
7 FRONT GRILLE	550.00	1 PC	550.00	✓
8 FRONT PANEL EMBLEM (FUSO)	70.00	1 PC	70.00	✓
9 FRONT WIPER GARNISH	180.00	1 PC	180.00	✓
10 FRONT PANEL (BIG)	1,200.00	1 PC	1,200.00	✓
11 FRONT RH CORNAL PANEL	270.00	1 PC	270.00	✓
12 AIRCON EVAPORATOR	980.00	1 PC	980.00	✓
13 AIR-CON GAS DISCHARGE HOSE	155.00	1 PC	155.00	✓
14 FRONT WINDSCREEN GLASS RUBBER	190.00	1 PC	190.00	✓
				4,990.00
Special Net				
15 FRONT NUMBER PLATE	35.00	1 PC	35.00	201m 35.00
Labour				
16 REMOVE AND REFIX FRONT WINDSCREEN RUBBER	100.00	1 LA	100.00	✓
17 REMOVE AND REFIX AIRCON, CHEMICAL VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
18 REMOVE & REFIX DASHBOARD, METER ASSY	280.00	1 LA	280.00	250/
19 PANEL BEATING AND STRAIGHTEN FRT RH WIND/SCREEN PILLAR	800.00	1 LA	800.00	700/
20 PUTTY AND RESPRAY ON FRT PANEL, CORNAL PANEL, FRT GRILLE, FRT RH WS PILLAR, FRT RH DOOR, FRT BUMPER, CABIN RR PAN EL	800.00	1 LA	800.00	720/
21 TO REMOVE ALUMINIUM CANOPY & ATTACHMENT, SUPPLY 1 SET ASSY FRT WOODEN STRUCTURE, FRT STRUCTURE BOARD AND INSTALLATION	1,700.00	1 LA	1,700.00	1400/
22 REMOVE ALUMINIUM CANOPY & ATTACHMENT; SUPPLY 2 SIDE SLIDING CANVAS, FRT WINDOW GLASS, 4 PCS PILLAR, 1 PC REAR ROLL DOWN CANVAS AND 1 SET ROOF TOP STRUCTURE ASSY	3,800.00	1 LA	3,800.00	3700/
Total				7,580.00
Add GST @ 7%				SS 12,605.00
Total Amount payable				882.35
				SS 13,487.35

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

YN 5744J
SUPP 1

M/S: SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555 FAX: 62213302
ATTN: Motor Claim Department

Claim No: ES2290577
Estimate No: ES2290577/YISHUN
Date: 15 Jun 2022
Policy No: D21MTPCVE001791
Veh Reg No: YN5744J
Make/Model: MITSUBISHI MIT.
CANTER
FEB21ER3SDEB
Chassis No: FEB21EA00702
Engine No: 4P10B30337
Reg. Date: 31/07/2014

WS Ref: OD/SOMPO
Claim Type: Own Damage
Accident Date: 01/06/2022

Estimate Repair Cost to Vehicle No : YN5744J

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
Supplementary 1				
Cost Plus				
1 FRT CABIN RH MOUNTING BRACKET	CM 480.00	1 PC	480.00	—
2 FRT CABIN RH MOUNTING	CM 150.00	1 PC	150.00	—
3 BRAKE PIPE	nd 180.00	1 PC	180.00	—
4 FRT RH DOOR INNERLOCK	nd 185.00	1 PC	185.00	—
5 CABIN REAR AIR DUCTING	CM 245.00	1 PC	245.00	—
				1,240.00

Total	S\$ 1,240.00
GST Amount	S\$ 86.80
Total Amount payable	S\$ 1,326.80

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE