

Lion City Rentals Pte Ltd
4 Jln Besut Singapore 619557
Main +65 62525525

Ms: China Taiping
Date 30/05/2022
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLC9420D
CHASSIS NO : GK81005546
MAKE / MODEL : Honda Shuttle Hybrid 1.5 CVT
DATE OF ACCIDENT: 23/05/2022
YOUR INSURED VEHICLE NUMBER: SLZ5501J
MILEAGE: 326353 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>	
1	R/L fender / <i>DD</i>	1PC	\$ 2,000.00	\$ 2,000.00	1172 ✓
2	R/L fender inner liner X <i>NN</i>	1PC	\$ 240.00	\$ 240.00	
3	R/L door / <i>DD</i>	1PC	\$ 1,575.00	\$ 1,575.00	1050 ✓
4	LH side skirt X <i>R</i>	1PC	\$ 750.00	\$ 750.00	
LIST TOTAL S\$:				\$ 4,565.00	2222
20.00% DISCOUNT S\$:				\$ 913.00	-20%
				\$ 3,652.00	1777.60

Steve (LKK)
10/6/22, 4.17pm

ML NL
L/S
M NL Y
5 dys

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SPECIAL NETT

1	Rear LH fender inner linear clips	X NN	1 SET	\$ 80.00
			Special Nett Total S\$:	\$ 80.00

LABOUR CHARGES

1	TO REMOVE FRONT BUMPER, F/L FENDER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS.	\$ 600.00	/
2	TO RESPRAY REAR LH FENDER, REAR DOOR LH and LH SIDE SKIRT	\$ 700.00	660
3	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS.	\$ 80.00	30
	LABOUR TOTAL S\$:	\$ 1,380.00	
	TOTAL S\$:	\$ 5,032.00	1290
	7% GST	\$ 352.24	
	GRAND TOTAL S\$:	\$ 5,384.24	

3067.60

L/S - 2454.08
= 2450