



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO22005537/Aqy3q2 Date: 06/12/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLH 7448L	Veh. Inspected	SKZ 7196E
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2201785/MYE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	10/06/2022
2. Vehicle Particulars & Condition			
Make & Model	VOLVO XC90	c.c	2521
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	YV1CZ595771392904	Colour	BLACK
Odometer	149119 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/60 R18	GOODYEAR	6 mm
L/H Front Tyre	235/60 R18	GOODYEAR	6 mm
R/H Rear Tyre	235/60 R18	GOODYEAR	6 mm
L/H Rear Tyre	235/60 R18	GOODYEAR	6 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.		
5. General Information			
Accident Date	22/05/2022	Inspection Date	13/06/2022
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		
5a. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days