



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

Our Ref : GBG9296T

Your Ref : S2M040C3

AXA INSURANCE SINGAPORE PTE LTD

27 June 2022

8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

Attn: MOTOR CLAIMS DEPT

Dear Sir / Madam,

RE: ACCIDENT INVOLVING VEHICLE NO.: GBG9296T & SHC8871P ON 30/04/2022 @ 13:45 HRS ALONG
BEDOK NORTH ROAD

The vehicle had been surveyed by your appointed surveyor and repaired to our client's satisfaction.

We hereby submit the details of claim as follow:

| | | |
|---|---|--------------------|
| Cost Of Repair | : | S\$4,440.50 |
| Loss Of Use (\$ 120.00 x 5 days) | : | S\$600.00 |
| Additional Loss Of Use (\$ 120.00 x 1 days) - Weekend | : | S\$120.00 |
| GIA / LTA Search | : | S\$7.45 |
| | | <u>S\$5,167.95</u> |

Kindly revert within SEVEN days. Failing which we reserve our rights to refer the matter to our solicitors.

Your kind attention to the matter would be much appreciated.

Yours faithfully,

TONG LUCK AUTO PTE LTD

AUTHORISATION LETTER

I, DAIMLER FLEET MANAGEMENT S'PORE PTE LTD of 1 GATEWAY DRIVE #15-08 WESTGATE TOWER SINGAPORE 608531, owner of GBG9296T hereby authorize TONG LUCK AUTO PTE LTD to act for me with my respect to our claim for repair costs and/or rental and/or loss of use for our vehicle no.: GBG9296T that was damaged pursuant to the accident which occurred on 30/04/2022 ALONG BEDOK NORTH ROAD involving vehicle nos: SHC8871P

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the

Dated this 8th day of June 2022


Signed by third party claimant




TONG LUCK AUTO PTE LTD





AXA THIRD PARTY DIRECT SETTLEMENT

| | | |
|-------------------------|----------------------|-------------------------------|
| Vehicle No: | SHC 8871P (Insd veh) | Model: NISSAN NV350 PANEL VAN |
| | GBG 9296T (TP veh) | 2.5 5AT 5DR EURO V |
| Date of Accident/ Time: | 30/04/2022 | |

| | | | |
|--|----------------------------------|---|-------------------------|
| Repair Estimate | : \$ | 9,633.32 | |
| Final Repair Cost w/GST | : \$ | 4,440.50 | |
| Loss of Use | : \$ | 400.00 | 5 days at \$ 80 per day |
| Rental (if any) | : \$ | | days at \$ per day |
| LTA / GIA Search Fee | : \$ | 7.45 | |
| Others: | : \$ | | |
| | : \$ | | |
| Final Settlement Sum | : \$ | 4,847.95 | |
| Payee Name : Tong Luck Auto Pte Ltd | | | |
| Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below) | | | |
| A) | For Non GIA Registered Workshop: | Agreed Liability 100 (%) | |
| B) | For GIA Registered Workshop: | BOLA Applicable: Yes/ No BOLA Scenario No: ____ | |
| | BOLA Liability: ____ (%) | Assessed Liability (*): ____ (%) | |
| * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply. | | | |
| Remarks: | | | |

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.


We/I confirmed that this is a **full and final settlement** that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative / Workshop stamp
Name of Representative: *Sandy Qy*
Date: *15/9/22*

Signature of Witness / Workshop stamp (if applicable)
Name of Witness: *Terence Tan*
Date: *15/9/2022*

Signature of AXA's surveyor/representative:
Name of AXA's surveyor /Representative:
Date: *16/09/2022*



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

TAX INVOICE

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

YOUR REF NO : S2M040C3

CLAIM TYPE : THIRD PARTY

ACCIDENT DATE : 30/04/2022

TP VEHICLE NO : SHC8871P

NO : AR202206-0066
CLAIM NO : QUOT202206-000022(01)
DATE : 27/06/2022
POLICY NO : 999995580
VEH REG : GBG9296T
MAKE/MODEL : NISSAN NV350 PANEL VAN
2.5 5AT 5DR EURO V
CHASIS NO : JN1MC2E26Z0009700
ENGINE NO : YD25002832B
REG. DATE : 2017

Final Repair Cost to Vehicle No : GBG9296T

| Description | Quantity | Unit Price | Amount |
|---|----------|------------|-----------------|
| | | <u>S\$</u> | <u>S\$</u> |
| NET PRICE | | | |
| 1 Tailgate | 1 | 2,597.90 | 2,597.90 |
| 2 Tailgate centre logo | 1 | 79.90 | 79.90 |
| 3 Tailgate 'NV350' emblem | 1 | 85.25 | 85.25 |
| 4 Tailgate 'URVAN' emblem | 1 | 85.25 | 85.25 |
| 5 Rear bumper | 1 | 667.20 | 667.20 |
| 6 Rear bumper retainer - LH | 1 | 181.00 | 181.00 |
| | | | <u>3,696.50</u> |
| | | Less 10% | <u>369.64</u> |
| | | | 3,326.86 |
| SPECIAL NET | | | |
| 7 Rear windscreen sealant | 1 | 40.00 | 40.00 |
| 8 Tailgate "70km/h" sticker | 1 | 12.00 | 12.00 |
| 9 Tailgate '5 pax' sticker | 1 | 12.00 | 12.00 |
| 10 Rear bumper clips (set) | 1 | 50.00 | 50.00 |
| | | | <u>114.00</u> |
| LABOUR | | | |
| 12 To remove and refit rear windscreen glass | 1 | 120.00 | 120.00 |
| 13 To transfer damaged tailgate interior mechanism to new tailgate | 1 | 60.00 | 60.00 |
| 14 To remove and refit rear bumper sensor | 1 | 50.00 | 50.00 |
| 15 To check and rectify wiring system | 1 | 15.00 | 15.00 |
| 16 To panel beat and straighten rear floorboard panel, LH rear rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same | 1 | 400.00 | 400.00 |
| 17 To putty and spray paint on affected areas | 1 | 400.00 | 400.00 |
| 18 To supply art works & paste decal on LH side panel and tailgate | 1 | 750.00 | 750.00 |
| | | | <u>1,795.00</u> |



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email : operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

TAX INVOICE

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

YOUR REF NO : S2M040C3

CLAIM TYPE : THIRD PARTY

ACCIDENT DATE : 30/04/2022

TP VEHICLE NO : SHC8871P

NO : AR202206-0066

CLAIM NO : QUOT202206-000022(01)

DATE : 27/06/2022

POLICY NO : 999995580

VEH REG : GBG9296T

MAKE/MODEL : NISSAN NV350 PANEL VAN
2.5 5AT 5DR EURO V

CHASIS NO : JN1MC2E26Z0009700

ENGINE NO : YD25002832B

REG. DATE : 2017

Final Repair Cost to Vehicle No : GBG9296T

| Description | Quantity | Unit Price | Amount |
|---------------------|----------|----------------|---------------------------|
| | | S\$ | S\$ |
| AMOUNT : | | | S\$ 5,235.86 |
| LUMP SUM DISCOUNT : | | | S\$ -1,085.86 |
| TOTAL : | | | S\$ 4,150.00 |
| ADD GST @ 7% : | | | S\$ 290.50 |
| GRAND TOTAL : | | | <u><u>S\$4,440.50</u></u> |

SINGAPORE DOLLARS FOUR THOUSAND FOUR HUNDRED AND FORTY AND CENTS FIFTY ONLY

TONG LUCK AUTO PTE LTD

E. & O.E.

AUTHORISED SIGNATURE

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 08 Jun 2022 / 13:58:21

Receipt Date/Time : 08 Jun 2022 / 13:58:21

Tax Invoice/Receipt

Receipt No. : ITNET-00000-220608-002100

Previous Receipt No. :

| S/N | Item Description/ Business Transaction Reference No. | Amount Before GST (\$\$) | GST Amount (\$\$) | Amount After GST (\$\$) |
|--|---|--------------------------------|-------------------------|-------------------------------|
| Result of Insurance Enquiry - SHC8871P | | | | |
| As at 30 Apr 2022/13:45:00 | | | | |
| Insurance Co: AXA INSURANCE PTE LTD | | | | |
| 1 | Insurance Enquiry - SHC8871P Enquiry Fee 20220608135652542862 | 7.00 | 0.49 | 7.49 |
| Sub-Total | | 7.00 | 0.49 | 7.49 |
| Total Before Rounding | | 7.00 | 0.49 | 7.49 |
| Rounding Difference | | | | 0.04 |
| Total Amount Payable | | | | 7.45 |
| Paid By | | | | |
| 518834XXXXXX2002 | | eNETS Credit Card | | 7.45 |
| Total | | | | 7.45 |
| Cash Change | | | | 0.00 |
| Tendered Amount | | | | 7.45 |
| Excess Refundable Amount | | | | 0.00 |

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Enquire Vehicle's Insurance Particulars

Thank You!

The insurance details of the vehicle you enquired can be found below. If you have entered a valid email address, a copy would have been sent to you.

Vehicle No.

SHC8871P

Incident Date/Time

30 Apr 2022 / 13:45:00

Insurance Company Name

AXA INSURANCE PTE LTD

[Save as PDF](#)

[OK →](#)

[Print](#)