LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

30 Jun 2022 Attn: Jowyn Tay Mei Ling Date:

Preliminary Advice

Insured Vehicle No : SLM9749D

TP Vehicle No : SLH7231U Accident Date : 11/06/2022 Make : MITSUBISHI LANCER Assignment Date : 15/06/2022

Date of Inspection : 13/06/2022 Est. Duration of Repair : 04

Inspection At : FASTECH AUTO PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,995.00
Revised Amount	:S\$	4,025.90
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,025.90
	0.0	0.000.00

Lump Sum Repair 3,200.00 :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

(X)	The vehicle is economical for repair
()	The vehicle is not economical for repair
()	Part-by-Part repair
(X)	Lump Sum repair

(X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check,part prices and labour cost.