



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|---|--|----------------|
| HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:KITTY | | | Ref: CC4/ASM22005581/Apa3q2 Date: 18/05/2023 Code: HSB | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SLT 5960Z | Veh. Inspected | GBJ 715U |
| | Policy No. | GA591430 | Coverage (\$) | 0.00 |
| | Claim No. | S2M043FE | Excess (\$) | 0.00 |
| | Assign From | | Assign Date | 07/06/2022 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | NISSAN NV200 | c.c | 1461 |
| | Engine No. | HIDDEN | Year of Reg. | 2018 |
| | Chassis No. | VSKYBAM20Z0174097 | Colour | GREY |
| | Odometer | 82729 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | NIL |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 175/70 R14C | ROADSTONE | 6 mm |
| | L/H Front Tyre | 175/70 R14C | ROADSTONE | 6 mm |
| | R/H Rear Tyre | 175/70 R14C | ROADSTONE | 6 mm |
| | L/H Rear Tyre | 175/70 R14C | ROADSTONE | 6 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 04/06/2022 | Inspection Date | 08/06/2022 |
| | Survey held at | AUTO UNITED SG PTE LTD 13 KAKI BUKIT ROAD 4, #03-29, BARTLEY BIZ CENTRE, SINGAPORE 417807 | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 14 Working Days | |