



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: GARNET LOW			Ref: CS/ASM22005657/Kvcm4 Date: 28/06/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBF 5221R	Veh. Inspected	SLP 8158A
	Policy No.	P2009272	Coverage (\$)	0.00
	Claim No.	S2M0442D	Excess (\$)	0.00
	Assign From	GARNET LOW (SMART CLAIMS)	Assign Date	15/06/2022
2. Vehicle Particulars & Condition				
	Make & Model	LEXUS UX250H (A)	c.c	1987
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	JTHY65BH002094563	Colour	METALLIC DARK GREY
	Odometer	23867 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 R18	BRIDGESTONE	7 mm
	L/H Front Tyre	225/50 R18	BRIDGESTONE	7 mm
	R/H Rear Tyre	225/50 R18	BRIDGESTONE	7 mm
	L/H Rear Tyre	225/50 R18	BRIDGESTONE	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/06/2022	Inspection Date	20/06/2022
	Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days