



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22005660/Ance2	
			Date: 12/01/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLJ 1742R	Veh. Inspected	SNF 1453Y	
Policy No.	D21MTPV01016107	Coverage (\$)	0.00	
Claim No.	CMTD2201914/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	15/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	PORSCHE MACAN	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2022	
Chassis No.	WP1ZZZ95ZNLB08883	Colour	BLACK	
Odometer	1253 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/40 R20	MICHELIN	8 mm	
L/H Front Tyre	295/40 R20	MICHELIN	8 mm	
R/H Rear Tyre	295/40 R20	MICHELIN	8 mm	
L/H Rear Tyre	295/40 R20	MICHELIN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/05/2022	Inspection Date	14/06/2022	
Survey held at	EUROKARS HABITAT PTE LTD NO.12 SUNGEI KADUT AVE SINGAPORE 729648			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	