

NGS MOTORSPORT PTE LTD

Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK AutoPoint Singapore 568047
 Tel :9695 5547 Fax: 6481 5727 e-mail : evelynnstrading@gmail.com
 Reg No: 201812604N

15/06/22

China Taiping Ins (S) Pte Ltd
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909
Attn: Motor Claims Dept

*Not Authorised
 L1 by \$1950k
 Penny after painting
 4 days*

RE: Accident On 10/06/22@07:28 ~~hrs~~ *PM*
 Ang Mo Kio Ave 3 Towards Hougang Ave 2
 Involving SJV2659C & SKM2282R
 Claims against SKM2282R (China Taiping)

We submit herewith our direct claim estimate quotation as follow:-

Replacement parts - KIA CERATO

1	Frt Fender LH				\$ ^R 407.50	X
1	Frt Door LH	<i>1017</i>			\$ 1,017.00	✓
14	Clips, Fender Lining		S.Nett	<i>10</i>	\$ 5.00	\$ 70.00 X
1	Rocker panel				\$ 474.50	✓
					\$ 1,969.00	
					Less 20%	\$ (236.06)

To remove frt damaged parts with all necessary components/
 attachments, repair/reshape dented body panel

\$ 800.00 *600*

Replace/reposition damaged parts, refit align into Refix all
 necessary components/attachment.

Transfer Door mechanism

\$ 150.00 *60*

Spray Painting - Frt Fender, Frt Door & Rocker Panel

\$ 800.00 *600*

\$ 4,027.44

Any other parts which necessitate repair or renewal will incur additional charged.
 Please contact our Ms Evelyn @HP96955547 to arrange for survey. Thank you

Yours faithfully,
NGS MOTORSPORT PTE LTD
 EVELYN NG

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: