

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Togs not recent to the recent									
Affiliated to Federation Internationale Des Experts En Automobile									
		INSURANCE (S) PL	Ref:	CS3/AGI22005694/y3					
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHOR 239924		Date	: 15/06/2022					
			Code	e: AGI					
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)								
	Insured Veh.	FBQ 5537Y	Veh. Inspected	SKP 2708P					
	Policy No.		Coverage (\$)	0.00					
	Claim No.	C20015707 /JT	Excess (\$)	0.00					
	Assign From	MAYBIE CHUA	Assign Date	15/06/2022					
2. Vehicle Particulars & Condition									
	Make & Model		c.c	0					
	Engine No.	HIDDEN	Year of Reg.						
	Chassis No.		Colour						
	Odometer	-	Steering						
	Brakes		Modification						
	General								
3.	3. Conditions of Tyres								
		Size	Make	Balance					
	R/H Front Tyre			mm					
	L/H Front Tyre			mm					
	R/H Rear Tyre			mm					
	L/H Rear Tyre			mm					
4.	Description of Damages								
_									
5.		General Information							
	Accident Date	03/06/2022	Inspection Date						
	Survey held at	PRECISE AUTO SERVICE							
		NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883							
5a.	Remarks								
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.								