



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22005696/Kvy3e2	
			Date: 14/06/2023	
			Code: SMO	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	GBE 5390R
	Policy No.	D21MTPCVE003085	Coverage (\$)	0.00
	Claim No.	CMTD2202073/AGC	Excess (\$)	500.00
	Assign From	GRACE TEO	Assign Date	15/06/2022
2. Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI CANTER (A)	c.c	2998
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	FEA01BA10141	Colour	WHITE
	Odometer	224925 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/70 R15	ARIVO	9 mm
	L/H Front Tyre	195/70 R15	ARIVO	9 mm
	R/H Rear Tyre	195/70 R15 (D)	ARIVO	9/9 mm
	L/H Rear Tyre	195/70 R15 (D)	ARIVO	9/9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/06/2022	Inspection Date	15/06/2022
	Survey held at	CHENG HOE MOTOR SERVICE BLK 1019, YISHUN INDUSTRIAL PARK A #01-374 SINGAPORE 768761		
5a. Remarks				
	A)THE MARKET VALUE IS S\$39,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	