

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBE5390R
OD/sompo

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555 FAX: 62213302
ATTN: Motor Claim Department

Claim No: ES2290591
Estimate No: ES2290591/YISHUN
Date: 15 Jun 2022
Policy No: D21MTPCVE003085
Veh Reg No: GBE5390R
Make/Model: MITSUBISHI MIT.
CANTER
FEA01BR1SDEB (CBU)
Chassis No: FEA01BA10141
Engine No: 4P10B83152
Reg. Date: 31/12/2015

WS Ref: OD/SOMPO
Claim Type: Own Damage
Accident Date: 13/06/2022

Estimate Repair Cost to Vehicle No : GBE5390R

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Cost Plus				
1 FRONT BUMPER	480.00	1 PC	480.00	
2 FRONT BUMPER LH BRACKET	75.00	1 PC	75.00	
3 FRONT BUMPER LH SIDE PAD	150.00	1 PC	150.00	
4 FRONT PANEL	1,200.00	1 PC	1,200.00	
5 FRONT PANEL EMBLEM (FUSO)	70.00	1 PC	70.00	
6 FRONT WIPER PANEL	600.00	1 PC	600.00	
7 FRONT WINDSCREEN GLASS	400.00	1 PC	400.00	
8 FRONT WINDSCREEN GLASS RUBBER	100.00	1 PC	100.00	
9 FRONT RH SIDE CORNAL GARNISH	250.00	1 PC	250.00	
10 HEADLAMPS	280.00	2 PCS	560.00	
11 RH HEADLAMP SIDE GARNISH	100.00	1 PC	100.00	
12 FRONT GRILLE	230.00	1 PC	230.00	
13 FRONT GRILLE EMBLEM (CANTER)	48.00	1 PC	48.00	
14 CABIN FRT MOUNTINGS	130.00	2 PCS	260.00	
15 CABIN FRT MOUNTING BRACKETS	450.00	2 PCS	900.00	
16 CABIN FRT MOUNTING COILS	15.00	2 PCS	30.00	
17 CABIN FRT MOUNTING CROSS BAR	280.00	1 PC	280.00	
18 CABIN FRT MOUNTING SHAFT	240.00	1 PC	240.00	
19 AIRCON EVAPORATOR	1,200.00	1 PC	1,200.00	
				7,173.00
Special Net				
20 ERP BRACKET	22.00	1 PC	22.00	
21 FRONT NUMBER PLATE	18.00	1 PC	18.00	
				40.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555 FAX: 62213302
ATTN: Motor Claim Department

Claim No: ES2290591
Estimate No: ES2290591/YISHUN
Date: 15 Jun 2022
Policy No: D21MTPCVE003085
Veh Reg No: GBE5390R
Make/Model: MITSUBISHI MIT.
CANTER
FEA01BR1SDEB (CBU)
Chassis No: FEA01BA10141
Engine No: 4P10B83152
Reg. Date: 31/12/2015

WS Ref: OD/SOMPO
Claim Type: Own Damage
Accident Date: 13/06/2022

Estimate Repair Cost to Vehicle No : GBE5390R

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
22 REMOVE AND REFIX FRONT WINDSCREEN GLASS	80.00	1 LA	80.00	
23 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	
24 REMOVE & REFIX DASHBOARD,METER ASSY AND CHECK WIRING	280.00	1 LA	280.00	
25 PANEL BEATING,INCLUDING STRAIGHTEN,KNOCK & REPAIR FRT RH W/SCREEN PILLAR AND REALIGN THE SAME	1,600.00	1 LA	1,600.00	
26 REMOVE & REFIX CABIN MOUNTING & CROSS BAR,STRAIGHTEN,KNOCK & REPAIR FRT CHASSIS AND REALIGN THE POSITION,INCLUDING REMOVE & REFIX CABIN	800.00	1 LA	800.00	
27 PUTTY & RESPRAY ON FRT PANEL,WIPER PANEL,FRT GRILLE,BUMPER,FRT RH W/SCREEN PILLAR,FRT RH DOOR,CABIN REAR RH PILLAR AND REAR PANEL	1,300.00	1 LA	1,300.00	
				4,160.00
			Total	S\$ 11,373.00
			Add GST @ 7%	796.11
			Total Amount payable	<u>S\$ 12,169.11</u>

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE