

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN		Ref:	CS/CTI22005704/Etc		
	3 ANSON ROAD #7 SPRINGLEAF TOW		Date:	15/06/2022		
				Code:	СТІ	
1.	. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	YM 7600H	Veh. Inspected		PC 9333A	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	SNM22D204149/C02/YM7600H/ THAMYL	Excess (\$)		0.00	
	Assign From	PAULINE THAM	Assign Date		15/06/2022	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes Modification			ition		
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	13/06/2022	Inspection Date	е	16/06/2022	
	Survey held at	566 WOODLANDS ROAD SINGAPORE 728697				
	Repairer	CONNECT3				
5a. Remarks						
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						