

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDD 8282G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	DEFORMED	1,514.00	1,514.00
2	REAR BUMPER SIDE RETAINER L/R @\$104.00 (CONSISTENT)	O/S DAMAGED	208.00	104.00
2	REAR BUMPER REVERSE SENSOR @\$254.00 (CONSISTENT)	DAMAGED (1 PIECE ONLY)	508.00	254.00
4	REAR BUMPER REVERSE SENSOR HOLDER @\$55.00 (CONSISTENT)	NECESSARY	220.00	100.00
1	REAR TAILLAMP RH (CONSISTENT)	NOT NECESSARY	689.00	-
1	REAR FENDER RH (CONSISTENT)	TO REPAIR SEE LABOUR	1,650.00	-
1	REAR FENDER INNER SHIELD RH (CONSISTENT)	NOT NECESSARY	219.00	-
1	REAR WHEEL BEARING WITH HUB RH (CONSISTENT)	NOT NECESSARY	320.00	-
	LESS 10% DISCOUNT		-532.80	-197.20
			4,795.20	1,774.80
	SPECIAL NETT ITEMS			
1	REAR SPORT RIM RH (SN) (CONSISTENT)	CUT	600.00	500.00
1	REAR TYRE RH (SN) (CONSISTENT)	NOT NECESSARY	300.00	-
1	REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR BUMPER SCUFF PLATE (SN) (CONSISTENT)	NECESSARY	250.00	180.00
1	REAR FENDER INNER SHIELD CLIP RH (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
			1,230.00	730.00
	<u>LABOUR</u>			
	TO CHECK WIRINGS.		80.00	30.00
	TO REMOVE AND REFIX REAR REVERSE SENSOR.		120.00	60.00
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANEL.		120.00	30.00
	TO STRAIGHTEN, REPAIR, REALIGN ON REAR AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER RH.		800.00	300.00
	TO SPRAY PAINTING ON AFFECTED AREA.		800.00	400.00
			1,920.00	820.00
	GRAND TOTAL		7,945.20	3,324.80

Report Ref No. CS/ASM22005719/Ancm4





RECOMMENDED COST OF LUMP SUM REPAIRS		2,600.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/ASM22005719/Ancm4



**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying o

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.