



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: ANG YVONNE			Ref: CS/ASM22005719/Ancm4 Date: 16/09/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7493D	Veh. Inspected	SDD 8282G	
Policy No.	VFX/P2419140	Coverage (\$)	0.00	
Claim No.	S2M043XZ	Excess (\$)	0.00	
Assign From	ANG YVONNE	Assign Date	15/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ B180	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WDD2462422J357668	Colour	GREY	
Odometer	127454 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	HABILEAD	6 mm	
L/H Front Tyre	225/45 R17	HABILEAD	6 mm	
R/H Rear Tyre	225/45 R17	HABILEAD	6 mm	
L/H Rear Tyre	225/45 R17	HABILEAD	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/06/2022	Inspection Date	15/06/2022	
Survey held at	SIN YU SIN WORKSHOP 1 KAKI BUKIT AVE 6 #01-82 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	