

ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	17:00hrs
ACCIDENT DATE	11-Jul-21
BUS CAPTAIN NAME	LOW ENG CHAI
OWN DAMAGE CLAIM AGAINST	MSFCL

BUS REGISTRATION NUMBER	SBS6329P
BUS TYPE (SD/DD)	SD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

SECTION 1 : MATERIALS, PARTS & CONSUMABLE ITEMS

NO.	Part or Item Description	Quantity	Total Cost
1	FRONT WINDSCREEN GLASS / OR	1	\$ 1,760.00
2	NSF QUARTER GLASS / OR	1	\$ 735.30
3	NS LH HEADLAMP / NSF OR	1	\$ 585.04
4	NS SIGNAL LIGHT / NSF CUT	1	\$ 91.18
5	NS MIRROR / MIS	1	\$ 2,359.00
6	FRONT BUMPER NS ANGLE / BT (BRAY)	1	\$ 253.00
7	CITARO SIGN / LOGO / NPL	1	\$ 212.20
8	NS FRONT BUMPER BRACKET (cloner) / BT	1	\$ 257.30
9	NSF BUMPER / OR	1	\$ 1,207.00
10	FRONT FLAP / OR (fml part)	1	\$ 1,525.00
11	OS WIPER ARM / NSF	1	\$ 267.80
12	NS WIPER ARM / OR	1	\$ 267.80
13	CLADDING (Rust M) / NSF	1	\$ 4,972.40
14	FRONT DOOR STEP EDGE / ?	1	\$ 140.80
15	BC SIDE PARTITION DOOR TOP COVER (Door upper part) / CRV	1	\$ 1,708.18
16	NS TOP ZB TRIM PANEL FIREWALL	1	\$ 362.40
17	NS EXTERIOR COVERING (fml pillar LH) / OR	1	\$ 381.46
18	FRONT BUMPER / OR	1	\$ 1,119.10
19	FRONT ENTRANCE DOOR BOTTOM SEAL FLAP / CRV	1	\$ 162.36
20	WIPER BLADE / CUT	2	\$ 92.70
21	FRONT TOP LAMP PARTITION MARKER (Rust top LH) / OR	1	\$ 86.16
22	TOWER TRANSIT LOGO (S) / NPL	1	\$ 100.00
23	SEALING FRAME WITH RUBBER COMPLETE SET (RH) / CUT	1	\$ 677.20
24	BRACKET - NS MIRROR / MIS	1	\$ 241.40
25	OS EXTERIOR COVERING (window lower part) / OR	1	\$ 341.00
26	CAB DRIVER DOOR PANELLING W/PIGEON HOLE (Door inner part) / CRV	1	\$ 1,209.46
27	WIPER ARM CAP / OR	2	\$ 19.20
28	SIKAFLEX / NPL	8 TUBES	\$ 300.00
		7% GST	\$ 1,500.41
		PARTS TOTAL COST	\$ 22,934.85

ESTIMATED ACCIDENT REPAIR COST



SECTION 2 : LABOUR COST - ASSESSMENT / REPAIR / SPRAY PAINT

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE ITEM NOS. 1- 27 <i>650 x 4.5</i>	\$ 3,250.00 <i>2925</i>
TO REMOVE & INSTALL PARTS AND TO PERFORM REPAIR WORKS :- • ENTRANCE DOOR PILLAR FRAME • FRONT DOME <i>650 x 1.5</i>	<i>975</i> \$ 2,600.00
SPRAY PAINTING ALL REPLACED AND REPAIRED PORTIONS <i>3-5 x 640</i>	<i>3520</i> \$ 6,400.00
SPRAY PAINTING \$640 PER PANEL LABOUR CHARGES \$650 PER DAY	7% GST \$ 857.50
	LABOUR TOTAL COST \$ 13,107.50

SECTION 3 : RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

SECTION 4 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

	DATE IN	13-Jun-2022
	DATE & TIME SURVEY	
	DATE OUT	
	TOTAL NUMBER OF DAYS	
BUS TYPE (SD / DD)	SD	
LOSS OF USE COST		

Steve CLKK
16 24/6/22, 11-22

00-M AL
Excell -?
LIS
4y AL y
12 dys

SUMMARY	
SECTION NO.	COST
1	\$ 22,934.85
2	\$ 13,107.50
3	-
4	\$ -
TOTAL	\$ 36,042.35