





## Yan (LKK Auto)

---

**From:** Judy Soh <judysoh@visionlawllc.com>  
**Sent:** Wednesday, 15 June 2022 11:12 AM  
**To:** 'assignments'; 'Summer (LKK Auto)'  
**Cc:** 'Sarjeet Singh'; 'Shanthi Marimuthu'; 'Foo Shu Hui'; 'Vithyanagan Pandian'; johnkhor90@gmail.com; 'Ravendra Krishnasamy'; sallychong@visionlawllc.com  
**Subject:** RE: RE-INSPECTION OF VEHICLE NO. SJZ 1200C | MC/MC 1794/2021 | VL REF: RK.scv.Ins-P48-112592-2020 (CHUA HUI XIN) II KCP REF : SS/sm/2021000465.Sompo(mpd)  
**Importance:** High

### FOR YOUR KIND ATTENTION

Dear Sirs,

**MC/MC SUIT NO. 1794 OF 2021**  
**CLAIMANT: CHUA HUI XIN**  
**ACCIDENT INVOLVING SJZ 1200 C & SLF 8031 J ON 31st DECEMBER 2019 AT ALONG PIE TRAVELING TOWARDS THOMSON ROAD EXIT AT ABOUT 17:25 HRS**

We refer to the above matter and the email from Kelvin Chia Partnership dated 14 June 2022.

Please be informed that the physical re-inspection of our client's vehicle SJZ 1200C has been arranged as follows:

Date	:	<b>20 June 2022 (Monday)</b>
Time	:	<b>11.30 a.m. to 2:00 p.m.</b>
Venue	:	<b>PRECISION MOTOR WORKS</b> 68 Kaki Bukit Ave 6 ARK @ KB 01-02 Singapore 417896
Contact	:	Mr. John Khor (Hp.: 8742 7247)

Thank you.

*Judy Soh*

(Secretary)  
VISION LAW LLC  
133 NEW BRIDGE ROAD,  
#18-01/02, CHINATOWN POINT,  
SINGAPORE 059413  
TEL.: 6534-2811 (ext 119)  
FAX : 6535-6802

---

**From:** Vithyanagan Pandian [mailto:vithyanagan.pandian@kcpartnership.com]  
**Sent:** Tuesday, 14 June, 2022 9:48 AM  
**To:** assignments; Summer (LKK Auto)  
**Cc:** Ravendra Krishnasamy; Sally; Judy Soh; Sarjeet Singh; Shanthi Marimuthu; Foo Shu Hui

**Subject:** SJE APPOINTMENT | MC/MC 1794/2021 | VL REF: RK.scv.Ins-P48-112592-2020 (CHUA HUI XIN) II KCP REF : SS/sm/2021000465.Sompo(mpdi)

**Email sent for and on behalf of Mr Sarjeet Singh, Kelvin Chia Partnership**

**Attention Mr. Bryan Ang**

**MC/MC 1794/2021**

Dear Mr Ang,

We refer to the above matter.

M/s Vision Law (copied herein) act for the Plaintiff (Owner and Driver of SJZ 1200C) and we act for the Defendant (Driver of SLF 8031J).

Please be informed that the court has appointed you, Mr. Bryan Ang, as the Single Joint Expert ("SJE") for this matter.

We enclose herewith copies of the following documents for your attention, kindly access the documents via the dropbox link: [https://www.dropbox.com/sh/u26zs64f8y1gby1/AAAd\\_AOr-e1SrgysYHcat-Va?dl=0](https://www.dropbox.com/sh/u26zs64f8y1gby1/AAAd_AOr-e1SrgysYHcat-Va?dl=0)

Singapore Accident Statement of SLF 8031J dated 2 January 2020 (with coloured photographs and Police Report);

Singapore Accident Statement of SJZ 1200C dated 3 January 2020 (with coloured photographs and Police Report);

Post-Accident Scene Photographs taken by the Defendant;

Dashboard Video Footage taken from SJZ 1200C and;

Priority Services Paper Survey Report of SJZ 1200C dated 27 April 2020.

Pleas liaise with M/s Vision Law (copied herein) for their survey reports and arrange for a physical re-inspection of SJZ 1200C and thereafter prepare an SJE report to record your findings.

Kindly bill the SJE Fees to Kelvin Chia Partnership.

Kindly acknowledge receipt of the assignment.

Thank you.

Kind regards,

**Vithyanagan (Mr.)**

**Paralegal. Any legal advice is rendered by the Partner, on whose behalf this email is issued.**

Note: In view of the current COVID-19 situation, we have adopted a telecommuting policy for our department. In the circumstances, kindly direct all communications to us via email with immediate effect.

**Lawyers**

[sarjeet.singh@kcpartnership.com](mailto:sarjeet.singh@kcpartnership.com)

**6408 7990**

[cynthia.lee@kcpartnership.com](mailto:cynthia.lee@kcpartnership.com)

**6408 7936**

[angelina.rajoo@kcpartnership.com](mailto:angelina.rajoo@kcpartnership.com)

**6408 7990**

**Secretaries**

[shanthi.marimuthu@kcpartnership.com](mailto:shanthi.marimuthu@kcpartnership.com)

**6408 7924**

[foo.shuhui@kcpartnership.com](mailto:foo.shuhui@kcpartnership.com)

**6408 7851**

**Paralegal**

[vithyanagan.pandian@kcpartnership.com](mailto:vithyanagan.pandian@kcpartnership.com)

**6408 7859**





LEGAL  
PARTNERS  
ACROSS  
ASIA

Kelvin Chia Partnership  
6 Temasek Boulevard  
29th Floor  
Suntec Tower Four  
Singapore 038986

Telephone: (65) 6220 1911  
Facsimile: (65) 6224 4118  
Direct dial: (65) 6408 7859  
Website: [kcpartnership.com](http://kcpartnership.com)

Singapore	Ho Chi Minh City	Phnom Penh
Bangkok	Jakarta	Shanghai
Hanoi	Mandalay	Yangon

CONFIDENTIALITY CAUTION:

This message is intended only for the use of the individual/entity to whom it is addressed and may contain information that is privileged and confidential. If you are not the intended recipient of this message, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify the writer immediately by return e-mail and delete the original message. Thank you.

---

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Address : 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

---

---

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---

Report No: 0022-20-PM

16 January 2020

## ACCIDENT VEHICLE SURVEY REPORT

Chua Hui Xin  
53 Lorong 40 Geylang #04-10  
Singapore 398077

### VEHICLE INFORMATION:

Vehicle Reg No.:	SJZ1200C	Odometer:	109705km
Make & Model:	BMW 730Li	Colour:	White
Chassis number:	WBAHN22010De96707	Date of accident:	31/12/2019
Year of Regn.:	26/04/2006	Date inspected:	08/01/2020
Repairer at:	Precision Motorworks 68 Kaki Bukit Ave 6 ARK @ KB #01-02 Singapore 417896	Date inspected (After Repair):	15/01/2020

### STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

### TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	5mm/Pirelli	5mm/Pirelli	245/40ZR20
Rear:	5mm/Pirelli	5mm/Pirelli	275/35R20

### POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the front LH portion.  
Please see details as described in the Annex for parts and labour.

### REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.



**PAR Automotive Consultancy****32****Parts and Labour Assessment**

Report No: 0022-20-PM

Vehicle No: SJZ1200C

Description of part	Qty	Condition as inspected	Repairer's estimate	Our adjustment
Front bumper fascia	1	squashed	1,500.00	1,500.00 R
Front bumper reinforcement	1	bent	771.13	771.13 HH
Front bumper side retainer LH	1	necessary	90.00	90.00 HH
Front bumper bracket LH	1	bent	95.00	95.00 HH
Front bumper protector LH	1	abraded	160.00	160.00 HH
Front bumper protector chrome	1	deformed	95.00	95.00 HH
Front bumper clip	10	necessary	30.00	30.00 SVC
Front bumper centre air grille	1	warped	125.00	125.00 HH
Front bumper headlamp nozzle	1	fractured	145.00	145.00 HH
Front bumper headlamp nozzle cover	1	ripped	70.00	70.00 HH
Front bumper sponge	1	fractured	120.00	120.00 SVC
Front fog lamp LH	1	fractured	280.00	280.00 HH
Front fog lamp cover LH	1	warped	75.00	75.00 SVC
Front headlamp LH	1	fractured	2,400.00	2,400.00 HH
Bonnet	1	repair	2,861.00	0.00 R
Bonnet logo "BMW"	1	necessary	58.85	58.85 ✓
Rear number plate garnish	1	fractured	75.00	75.00 ✓
<i>Subtotal before discount</i>			8,950.98	6,089.98
<i>Percentage discount 0% and 0%</i>			0.00	0.00
<b>Sub-total 1</b>			<b>8,950.98</b>	<b>6,089.98</b>
Front bumper parking sensor	2	shorted	760.00	760.00 SVC
Front number plate	1	bent	45.00	40.00 ✓
<i>Subtotal before discount</i>			805.00	800.00
<i>Percentage discount 0% and 0%</i>			0.00	0.00
<b>Sub-total 2</b>			<b>805.00</b>	<b>800.00</b>
<b>Parts-total</b>			<b>9,755.98</b>	<b>6,889.98</b>
<b>LABOUR</b>				
1. To straighten and panel beating bonnet, front support panel, front fender LH and front LH frame members. To remove and refit above parts.			1,200.00	660.00 500/-
2. To putty, re-spray painting and polish affected areas.			1,200.00	880.00 500/-
3. To check and rectify wiring system.			80.00	40.00 ✓
4. To analysis and reset electrical module system.			380.00	380.00 180/-
<b>Labour total</b>			<b>2,860.00</b>	<b>1,960.00</b>
<b>Parts &amp; Labour total</b>			<b>12,615.98</b>	<b>8,849.98</b>

91P 1,393.85

3 days

# PAR Automotive Consultancy

33

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on LUMP SUM repairs is :  
and the recommended number of working days for the repairs is :

\$7,000.00

6



B J Loi (I Eng. MIMI, AIRTE)  
Automotive Appraiser