



[Handwritten signature]

16 June 2022

China Taiping - LKK

3rd Party Claim - Motor Claims Department

ESTIMATES FOR SJT6221R - Honda Civic FD4 1.6A OCT 2009

COE OCT 2024

Chassis No: JHMF46209S200399

List Items

S/N	QTY	Description	Unit Price	Amount
1	1	front bumper <i>Distorted</i>	980.00	\$980.00 638.
2	2	front bumper retainers <i>new</i>	65.00	\$130.00 90.
3	1	front bumper clips (set) <i>new</i>	50.00	\$50.00 30.
4	1	front bumper lower grille <i>new</i>	220.00	\$220.00 85.
5	1	front bumper fog lamp garnish RH <i>Del'd</i>	120.00	\$120.00 85.
6	1	front bumper number plate garnish <i>new</i>	180.00	\$180.00 180.
7	1	top grille base <i>Del'd</i>	220.00	\$220.00 220.
8	1	top grille logo - emblem <i>new</i>	62.00	\$62.00 62.
9	1	top grille chrome <i>Not new Del'd</i>	350.00	\$350.00 184.
10	2	headlamps LH & RH <i>Del'd</i>	710.00	\$1,420.00 55.
11	2	headlamp lower brackets <i>RH Bent</i>	95.00	\$190.00 190.
12	1	support panel <i>Repair</i>	480.00	\$480.00 480.
13	1	support panel top garnish <i>Gap</i>	175.00	\$175.00 175.
14	1	support panel top garnish clips (set) <i>new</i>	50.00	\$50.00 50.
15	1	front reinforcement bar <i>Del'd</i>	380.00	\$380.00 380.
16	2	front air vent garnishes <i>new</i>	60.00	\$120.00 120.
17	1	front fender RH <i>Del'd</i>	440.00	\$440.00 440.
18	2	front fenders liner splash shield LH & RH <i>RH Del'd</i>	275.00	\$550.00 390.
19	2	front fender liner clips (set) LH & RH <i>new</i>	60.00	\$120.00 120.
20	1	aircon condensor <i>Gap</i>	950.00	\$950.00 950.
21	2	aircon condensor mountings <i>new</i>	45.00	\$90.00 90.
22	1	aircon inlet pipe <i>Gap</i>	240.00	\$240.00 240.
23	1	aircon outlet pipe <i>new</i>	240.00	\$240.00 240.
24	1	radiator assembly	1,080.00	\$1,080.00 1,080.
25	1	bonnet <i>Repair</i>	880.00	\$880.00 880.
26	1	bonnet heat shield <i>Gap</i>	260.00	\$260.00 260.
27	1	bonnet heat shield clips (set) <i>new</i>	100.00	\$100.00 100.
28	2	bonnet hinges	50.00	\$100.00 100.
29	1	front undercarriage cover garnish centre <i>Del'd</i>	210.00	\$210.00 210.
30	2	front splash shield front cover garnish LH & RH <i>new</i>	85.00	\$170.00 170.
31				\$0.00
32				\$0.00
33				\$0.00
34				

Total before discount: \$10,557.00

Less 20%: -\$2,111.40

Sub Total: \$8,445.60

4319.

3455.20



SPECIAL NETT ITEMS

S/N	QTY	Description	Price
1	1	vacuum and refill aircon gas <i>for</i>	\$100.00
2	1	radiator coolant	\$100.00
3	1	android radio head unit faulty - cannot auto start <i>He n</i>	\$330.00
4			
Total:			\$530.00

LABOUR & MISC. CHARGES

S/N	QTY	Description	Price
1		panel beating	\$1,000.00 500
2		spray painting	\$1,300.00 600
3		headlamp x2 focusing setting	\$80.00 30
4		remove & refit front bumper attachments	\$80.00 +
5		rustproofing	\$100.00 50
6			
Total:			\$2,560.00

Grand Total: \$11,535.60

Lump Sum -20% : \$9,228.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Gij
h/s 16/06/22.
05 Pages

total: 4635.20
h/s: 3.7K.