

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0485/2022/JT
DATE : 10-Jun-22
WIP : 28173

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 15/6/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

4 days - ok - Johnny Boo

16-Sep-22

OWNER'S NAME : MS. PRIYA VERMA
ADDRESS : 134, TANJONG RHU RD
SINGAPORE 436920
TELEPHONE : HP +65 9231 4204
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 721001283
VEHICLE NO : **SMX 8198 E**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 29/1/2021
ENGINE NO : CZD C23285
CHASSIS NO : WAUZZZF36M1058954
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Jun-22
PLACE OF ACCIDENT : KALLANG WAVE MALL CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 8198 E

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00	\$ 280.00
2	TO DISMANTLE AND RENEW LHS REAR DOOR. TO REPAIR LHS REAR FENDER, LHS SILL PANEL AND DOOR ENTRANCE. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,500.00	\$ 1,000.00
3	TO RESPRAY LHS REAR DOOR, LHS REAR FENDER, LHS SILL PANEL, DOOR HANDLE AND DOOR ENTRANCE.	\$	3,500.00	\$ 1,300.00
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	6,592.00	\$ 2,772.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 8198 E

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR DOOR - LH	1	\$ 3,127.00	\$	2,501.60
2	REAR DOOR OUTER SEAL - LH	1	\$ 151.00	\$	120.40
3	REAR DOOR CATCH	1	\$ 134.00		
4	REAR DOOR SEAL INNER - LH	1	\$ 213.00		
5	REAR SILL PANEL SEAL - LH	1	\$ 151.00		
6	REAR DOOR COVER - LH	1	\$ 270.00	\$	216.00
7	REAR DOOR WINDOW REGULATOR - LH	1	\$ 302.00		
8	REAR WHEEL ARCH COVER - LH	1	\$ 283.00	\$	226.00
9	GROMMET	2	\$ 7.00	\$	4.96
10	REAR DOOR HANDLE, EXTERIOR - LH	1	\$ 222.00		
11	REAR DOOR HANDLE HOUSING - LH	1	\$ 31.00		
12	REAR WHEEL HOUSING LINER	1	\$ 262.00		
13	REAR WHEEL SPOILER - LH	1	\$ 44.00		
14	SIDE MEMBER TRIM - LH	1	\$ 189.00		
15	STONE CHIP	S/N	\$ 180.00		
16	SUNDRIES		\$ 350.00	\$	7.20
TOTAL SPARE PARTS		:	\$ 5,916.00	\$	3,076.16
TOTAL LABOUR CHARGES		:	\$ 6,592.00	\$	2,772.00
GRAND TOTAL		:	\$ 12,508.00	\$	5,848.16

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-19/09/22



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT