



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22005760/Evy3e2	
			Date: 05/07/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 5069R		Veh. Inspected	SGU 639P
Policy No.			Coverage (\$)	0.00
Claim No.	D22001825MFCV		Excess (\$)	0.00
Assign From	AINI BINTE		Assign Date	16/06/2022
2. Vehicle Particulars & Condition				
Make & Model	AUDI A6		c.c	1798
Engine No.	HIDDEN		Year of Reg.	2016
Chassis No.	WAUZZZ4G3GN071504		Colour	WHITE
Odometer	97495 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	FAIR			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		205/55 R16	MICHELIN	5 mm
L/H Front Tyre		205/55 R16	MICHELIN	5 mm
R/H Rear Tyre		205/55 R16	MICHELIN	5 mm
L/H Rear Tyre		205/55 R16	MICHELIN	5 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/06/2022		Inspection Date	27/06/2022
Survey held at	WAH HONG MOTORS & CREDIT PTE LTD 38 TOH GUAN ROAD EAST #01-57 ENTERPRISE HUB SINGAPORE 608581			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	