



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SGU639P AUDI A6 TSFI

Page No. 3

QTY	DESCRIPTION (SUPPLEMENTARY)	CONDITION	REPAIRER'S ESTIMATE(\$\$)		SURVEYOR'S ADJUSTMENT	
2	<u>PARTS (LIST ITEMS)</u>	Part Items Total:	312.00		✓ broken	
	Rear bumper lower side bracket LH/RH @2*\$156		-5%	312.00		
				-15.60		
				296.40		
	<u>SPECIAL NETT ITEMS</u>					
	<u>LABOUR</u>					
		</				