



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

SOMPO INSURANCE SINGAPORE PL	Ref: CS/SMO22005762/Avy3
50 RAFFLES PLACE #03-03	Date: 16/06/2022
SINGAPORE LAND TOWERSINGAPORE 048623	Code: SMO

**1. Policy Particulars :- THIRD PARTY CLAIM**

<b>Insured Veh.</b>	PH 8811S	<b>Veh. Inspected</b>	GBE 1870Z
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CMTD2202094/THE	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	GRACE TEO	<b>Assign Date</b>	16/06/2022

**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b>		<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>		<b>Colour</b>	
<b>Odometer</b>	-	<b>Steering</b>	
<b>Brakes</b>		<b>Modification</b>	
<b>General</b>			

**3. Conditions of Tyres**

	Size	Make	Balance
<b>R/H Front Tyre</b>			mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>			mm
<b>L/H Rear Tyre</b>			mm

**4. Description of Damages**

--

**5. General Information**

<b>Accident Date</b>	15/06/2022	<b>Inspection Date</b>	17/06/2022
<b>Survey held at</b>	D&K AUTOMOTIVE SERVICES PTE LTD 232 HOUGANG AVENUE 1, #12-232, SINGAPORE 530232		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--