MOTORIMAGE ENTERPRISES PTE. LTD. 25 LENG KEE ROAD SINGAPORE 159097

FINALIZED

: ACCIDENT/BODY REPAIRS

WORKSHOP

REFERENCE

: LENG KEE

CONTACT NO :

: INS/IC/CHI/0107/2022

DATE

: 14-JUN-2022

HL ASSURANCE PTE LTD 11 KEPPEL ROAD, #11-01

ABI PLAZA S(089057)

TEL: 6702 0202 FAX: 6922 6002

OWNER'S NAME

: CHAN HOON HOON

ADDRESS

: APT BLK 458 ANG MO KIO AVENUE 10

#07-1588

S(560458)

TELEPHONE NO

: 9777 5123

TYPE OF CLAIM : THIRD PARTY CLAIM

POLICY NO : 2070160356-01

VEHICLE NO

: SLE7373J

MODEL CODE

: GT7DKVL

MODEL/YEAR

: SUBARU XV 2.01-S EYESIGHT AWD CVT

ENGINE NO CHASSIS NO

: FB20CG88046

MILEAGE

: JF1GT7KL5LG094351

DATE IN

: 1 KM : 14/06/2022

LIABILITY

: 0.00

EXCESS CLAUSE :

0.00

ESTIMATE BY - : MOHAMED ISMAN BIN MOHAMED HEPBUN**

ACCIDENT DATE : 12/06/2022

Print Date Print Time

: 12/12/2022 : 13:57:39

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLE7373J

		NATURE OF JOB	CHARGES	SURVEYOR'S RECOMMENDATION
	TPCLAIM			
2	ZZ/001	CONDUT TP CLAIM HL ASSURANCE DATE:12/06/2022 TIME: 1338HRS LOCATION:BISHAN ST 22 SLIP RD TO BISHAN RD		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER, PANEL & TAILGATE	1680.00	1120.00
4	ZZ/003	RESPRAY REAR BUMPER, PANEL & TAILGATE	1260.00	840.00
5	ZZ/004	REMOVE & REFIX EXHAUST	150.00	.00
6	ZZ/005	TRANSFER TAILGATE MECHANISM	150.00	150.00
7	ZZ/006	WHEEL ALIGNMENT	200.00	.00
8	ZZ/007	FAULT DIAGNOSTIC	280,00	.00
9	ZZ/008	REMOVE & INSTALL REAR WINDSCREEN	300.00	300.00
10 7	ZZ/009	CONDUCT REAR LIGHTING TEST	50.00	50.00
11 2	ZZ/011	SUPLLY & INSTALL REAR WINDSCREEN TINTED FILM	145.00	145.00
12 2	77/012	SUNDRIES	100.00	20.00
13 2	ZZ/013	REPAIR REAR END PANEL (SUPP) (supplementary)	280.00	280.00 🗸
14 Z	ZZ/014	RESPRAY REAR BUMPER BEAM & END PANEL (SUPP) (supplem	420.00 nentary)	420.00 🗸
15 Z	ZZ/10	SUPPLY & INSTALL REVERSE SENSOR - 4 EYES	400.00	400.00
		TOTAL LABOUR CHARGES	5415.00	3725.00
			J71J.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLE7373J

DAMAGED	DADTS	٧.	DDICES	2
DAMAGED	PARIS	N	PRILLE	٦.

S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT		S/LIST REMARKS
1 BUMPER PUNCHING RXV	57702FL220	414.40		0K
2 BRKT SD R XV RH	57707FL400	12.40		χ
3 BRKT SD R XV LH	57707FL410	12.40		Х
4 BRKT LWR R X2	57707FL510	26.00		ОК
5 BEAM COMPL R EU	57711FL0419P	208.60		OK
6 COVER SD LWR XV RH	57731FL500	21.50		χ
7 COVER SD LWR XV LH	57731FL510	21.50		Χ
8 COVER HOOK R XV	57731FL570NN	6.70		χ
9 PANEL COMPL R GAT ORDER TCS	60809FL0009P	940.00		OK
10 GLASS ASSY R G	63019FL030	1091.50		OK
11 STRIKER R/G	63264AG100	22.20		Х
12 WSTR DR R G	63516FL000	111.00		Χ
13 DAM RUBBER	65245FL000	18.50		OK
14 LENS & BODY COMPLLH	84912FL210	199.80		Χ
15 LENS & BODY COMPLRH (supplementary) BR	84912FL2 40	370.00 🗸		OK
16 LENS & BODY COMPLLH	84912FL251	370.00		Х
17 LENS & BODY COMPLRRH	84913AL120	133.20		OK
18 LENS & BODY COMPLRLH	84913AL140	66.60		Х
19 SNR SENS ASSY (SUPP) (supplementary) BR	87621FL000EN	233.10 🗸		ОК
20 SNR CAP ASSY (SUPP) (supplementary) BR	87623FL000EN	37.00 🗸		OK
21 GARNISH SC	91111FL030NN	178.70		Х
22 ORNAMENT ASSY F SIX (supplementary) NEC	91174SA181	70.30 🗸		OK
23 LETTER MK R (supplementary) NEC	93079FL100	92.50 🗸		OK
24 LETTER MK R XV (supplementary) NEC	93079FL140	37.00 🗸		ОК
25 TRIM PNL AY SKIRTT	94026FL010VH	111.00		Х

DAMAGED	PARTS	8	PRICES	
---------	-------	---	--------	--

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST	REMARKS	
26	EYE SIGHT EMBLEM (TCS) (SUPP)(supplementary)NECLPH010ES-EMB	44.40 🗸				OK	
	SUB TOTAL		3716.50	0.00	0.00	0.00		
	LESS DISCOUNT (NETT-20 %)		743.30	0.00	0.00	0.00		
	GRAND TOTAL		2973.20	0.00	0.00	0.00		

	OVERALL TOTAL		2973.20					

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD. 25 LENG KEE ROAD SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLE7373J

NETT ITEM	3716.50
LESS 20 %	-743.30
NETT AMOUNT	2973.20
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	0.00
S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00
TOTAL LABOUR CHARGES	3725.00
TOTAL SPARE PARTS CHARGES	2973.20
TOTAL CHARGES	6698.20
ADD 7 % GST	468.87
GRAND TOTAL	7167.07