



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22005770/Kqy3 Date: 17/06/2022 Code: SMO	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SLE 5555P
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2202090/RUC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	17/06/2022
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	15/06/2022	Inspection Date	17/06/2022
	Survey held at CHENG HOE MOTOR PL 38 WOODLANDS INDUSTRIAL PARK E1 #05-04/05 SINGAPORE 757700			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				