



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
-			Ref:	CS/TP22005775/Uqy3e2
BETHLEHEM AUTO BLK 5035 ANG MO KIO INDUSTRIAL PARK2 #01-371SINGAPORE 569538			Date:	20/06/2022
			Code:	TP2
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	Veh. Inspected	SKU 661B	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	08/06/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA PRIUS ALPHA HYBRID (A)	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	ZVW400029632	Colour	SILVER
	Odometer	294100 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	RAPID	5 mm
	L/H Front Tyre	205/55 R16	RAPID	5 mm
	R/H Rear Tyre	205/55 R16	RAPID	5 mm
	L/H Rear Tyre	205/55 R16	RAPID	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	06/06/2022	Inspection Date	08/06/2022
	Survey held at	BETHLEHEM AUTO 5035 ANG MO KIO INDUSTRIAL PARK 2 #01-371 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569538		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	