

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD		Ref:	CC4/ASM22005779/Apa3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	13/12/2022	
	ATTN: YVONNE A	NG		Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHD 6846X	Veh. Inspected	ł	SMY 9939Y	
	Policy No.	P2465714	Coverage (\$)		0.00	
	Claim No.	S2M044CG	Excess (\$)		0.00	
	Assign From		Assign Date		17/06/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA CIVIC TURBO	c.c		1498	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	MRHFK4840HT000025	Colour		WHITE	
	Odometer	32340 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/50 R17	YOKOHAMA		6 mm	
	L/H Front Tyre	215/50 R17	YOKOHAMA		6 mm	
	R/H Rear Tyre	215/50 R17	YOKOHAMA		6 mm	
	L/H Rear Tyre	215/50 R17	YOKOHAMA		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	15/06/2022	Inspection Dat	e	20/06/2022	
	Survey held at	TEAMWORK GARAGE PTE LTD				
		53 UBI AVENUE 1 #01-24 SINGAPORE 408934.				
5a.	Remarks					
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair					
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		10 Work	king Days	