



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR22001970/Eqy3 CS3/SMR22001970/Eqy3-1	Date: 02/03/2022
			Code: SMR	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SHB 591E	Veh. Inspected	SLX 2965J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D22000564MFSH/STRIDES/EL	Excess (\$)	0.00	
Assign From	HUA YEN ASHLENE LEE	Assign Date	02/03/2022 15/06/2022	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/02/2022	Inspection Date	04/03/2022	
Survey held at	CHEONG AUTO PTE LTD 262 QUEENSWAY SINGAPORE 149061			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				