



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 ATTN: SALIHA SYED		Ref: CS3/AIG22000137/Gty3e2-1 Date: 20/06/2022 Code: AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMM 7145Y	Veh. Inspected	SKV 5231X
Policy No.	0999993611	Coverage (\$)	0.00
Claim No.	8154280459SG	Excess (\$)	0.00
Assign From	SALIHA SYED	Assign Date	24/05/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS HYBRID 1.8	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	ZVW305757972	Colour	WHITE
Odometer	100600 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/45 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/45 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/45 R17	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/01/2022	Inspection Date	05/01/2022
Survey held at	LYE DESIGNS 10, AMK AUTOPOINT, 04-04 ANG MO KIO IND PARK 2A, SINGAPORE 568047		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	