

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 09/07/2022

User ID PohSuan

Section A - Accident Details

Registration Number	SHB1700B
Case Reference Number	TAX/06/22/2047
Registration Date	30/11/2021
Company Type	Strides Taxi Pte Ltd
Make	MORRISGARAGES
Model	MG5
Name of Driver	RICHARD TAN KUAN HENG
Type of Accident	Side Swipe
Accident Date and Time	18/6/2022 10:12 AM
Accident Reported Date and Time	18/6/2022 11:34 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24115339
Special Instruction to ARC, if any	TP
Prepared Date and Time	18/6/2022 12:18 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$3,600.00	\$300.00
Total Spray Cost	\$1,284.00	\$660.00
Total Spare Part Cost	\$5,198.64	\$21.60
Total Other Cost	\$965.00	\$300.00
TOTAL COST	\$11,047.64	\$1,281.60 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / China Taiping
ARC / Surveyor Sign Off Date	18/06/2022 12:41 PM	20/06/2022 2:16 PM
Signature		
Remarks	PART BY PART REPAIR / RESURVEY AFTER PAINT / REPLACE ITEM NEED NEW PART AND OLD PART PHOTO .	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2207-0036	Invoice Number	
Quotation Date	06.07.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION RH	\$3,600.00	\$300.00
Total Labour	\$3,600.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$428.00	\$220.00
TO RESPRAY RH REAR DOOR	\$428.00	\$220.00
TO RESPRAY REAR FENDER RH	\$428.00	\$220.00
Total Spray Painting & Panel Beating	\$1,284.00	\$660.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$0.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$150.00
ISOLATED OF (EV) (NET)	\$150.00	\$150.00
TO REMOVE & REFIT REAR QUARTER GLASS RH	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
Total Other Costs	\$965.00	\$300.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		10374913	MOLDING ASM-RR S/D WDO UPR RVL-RH	0.00	\$54.50	0.00	\$0.00	Replace	Not Given
		10285737-SPRP	HANDLE ASM-FRT S/D O/S - RH	0.00	\$36.92	0.00	\$0.00	Replace	Not Given
		10285746-SPRP	COVER-RR S/D LK CYL-RH	0.00	\$14.88	0.00	\$0.00	Replace	Not Given
		10246254	STRIKER-FRT S/D LK	0.00	\$16.74	0.00	\$0.00	Replace	Not Given
		10383922	CHECK ASM-RR S/D -RH	0.00	\$21.00	0.00	\$0.00	Replace	Not Given
		10364952-SEPP	HINGE ASM-RR S/D UPR-RH	0.00	\$46.90	0.00	\$0.00	Replace	Not Given
		10364954-SEPP	HINGE ASM-RR S/D LWR-RH	0.00	\$47.22	0.00	\$0.00	Replace	Not Given
		10322238	WINDOW ASM-QTR - RH	0.00	\$251.48	0.00	\$0.00	Replace	Not Given
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given
		10380138-SEPP	DOOR ASM-RR SI -RH	1.00	\$2,185.04	100.00	\$0.00	Replace	Repair
		10720690-CC-SEPP	PANEL-BODY SI OTR RR FENDER - RH	1.00	\$977.08	100.00	\$0.00	Replace	Repair
			STICKER ELECTRIC (LOGO	1.00	\$21.60	0.00	\$21.60	Replace	Replace
		10626941	LINER ASM-RR W/H PNL -RH	0.00	\$85.48	0.00	\$0.00	Replace	Not Given
		10369261-SPRP	FASCIA-RR BPR	1.00	\$758.48	100.00	\$0.00	Replace	Repair
		10326371	BRACKET-RR BPR FASCIA SI MTG - RH	0.00	\$46.08	0.00	\$0.00	Replace	Not Given

X
X
X
X
X
X
X
X
X
X
R
R
√ nec
X
R
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 09/07/2022

User ID : PohSuan

		10760960	REGULATOR ASM-RR S/D WDO-RH	0.00	\$265.30	0.00	\$0.00	Replace	Not Given
		10297708	LATCH ASM-RR S/D -RH	0.00	\$139.98	0.00	\$0.00	Replace	Not Given
		10587410	LAMP ASM-TAIL(BODY SI) - RH	1.00	\$764.08	100.00	\$0.00	Replace	Repair
Total					\$5,769.76		\$21.60		

X
X
R

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

21.60
+ 300.00
+ 960.00

1,281.60