Yan (LKK Auto)

From: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sq>

Sent: Monday, 20 June 2022 10:11 AM

To: 'SUR'; 'assignments'

Cc: Hwang, Shiang Yi; Teo, Grace; erzat@erzatleemotor.com; suria@erzatleemotor.com;

claim@erzatleemotor.com; Nur Hidayah

Subject: RE: SOMPO REF CMTD2201588 Our ref: FBC 3407B; Your ref YN5530J: CUSTOMER:

NOOR AZMAN BIN MOENIR - ACCIDENT INVOLVING VEHICLE NO.FBN 3407B AND VEHICL NO. YN5530J AT CENTRAL EXPRESSWAY ON 08 MAY 2022 AT 19:30 HRS-

NOTICE FOR PRE REPAIR INSPECTION

Dear LKK Auto,

Please make the arrangement to survey for FBC3407B by Mr Kenneth and revert with your preliminary report upon completion of survey to my colleague, Shiang Yi.

Thank you.

Working From Home with effect from 06 April 2020 till further notice

<u>Please be informed that our office will relocate to #03-03 at Singapore Land Tower with effect from 1 Dec 2020. Kindly direct invoices and business correspondence to our new registered address.</u>

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | **T**: 6461 6555



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #03-03 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy.

From: Nur Hidayah hidayah@erzatleemotor.com

Sent: Monday, June 20, 2022 9:31 AM

To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Cc: Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>;

erzat@erzatleemotor.com; suria@erzatleemotor.com; claim@erzatleemotor.com

Subject: Re: SOMPO REF CMTD2201588 Our ref: FBC 3407B; Your ref YN5530J: CUSTOMER: NOOR AZMAN BIN MOENIR

- ACCIDENT INVOLVING VEHICLE NO.FBN 3407B AND VEHICL NO. YN5530J AT CENTRAL EXPRESSWAY ON 08 MAY 2022 AT 19:30 HRS-NOTICE FOR PRE REPAIR INSPECTION

CAUTION: This Email is from an EXTERNAL source. Ensure you trust this sender (Email) before replying or clicking on any links and open attachments.

WITHOUT PREJUDICE

Our Reference: CMTD2201588/SYH

Your Reference: FBC3407B

Hi Sir

We would like to appoint **Kenneth** from **LKK** for the Surveyor.

Thank You

Best Regards,
Nur Hidayah
Administrative Executive

Erzat Lee Motor Trading Pte Ltd Synergy@KB 23 Kaki Bukit Road 4 #01-19 Level 2 Singapore 417801 E: Hidayah@erzatleemotor.com

[This e-mail is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you]

On Mon, 20 Jun 2022 at 08:22, Ye, Yong Kang Melvin < melvin.ye@sompo.com.sg > wrote:

Our Reference: CMTD2201588/SYH

Your Reference: FBC3407B

Without Prejudice

Date: 20.06.2022

Attention:
M/S ERZAT LEE MOTOR TRADING PTE LTD
Dear Hidayah,
ACCIDENT INVOLVING FBC3407B & YN5530J ON 08.05.2022
We refer to your Notice of Accident dated 20/06/2022.
Please be informed that Ms Hwang Shiang Yi is the handler of this case.
We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.
Selection (Indicate as

	Motor Surveyor	Surveyor	tick)
		Kenneth Kong Seng	
1	LKK Auto Consultants	Cheong	
		Marcus Chua Kang Seng	
		Adrian Ling	
2	Priority Services	Jimmy Lee	
3	Raleigh Services	Andrew Ow Yong	
4	RT Appraisal Pte Ltd	Ricky Teng	
		Elgene	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Working From Home with effect from 06 April 2020 till further notice

Please be informed that our office will relocate to #03-03 at Singapore Land Tower with effect from 1 Dec 2020. Kindly direct invoices and business correspondence to our new registered address.

Best Regards
Melvin Ye

Claims Division

D: 6322 4667 | **T**: 6461 6555



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #03-03 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy.

From: Nur Hidayah hidayah@erzatleemotor.com

Sent: Friday, June 17, 2022 4:25 PM

To: claimsreport < claimsreport@sompo.com.sg >

Cc: Erzat Lee <<u>erzat@erzatleemotor.com</u>>; Suria Suria <<u>suria@erzatleemotor.com</u>>; Claim Motor

<<u>claim@erzatleemotor.com</u>>

Subject: Our ref: FBC 3407B; Your ref YN5530J: CUSTOMER: NOOR AZMAN BIN MOENIR - ACCIDENT INVOLVING VEHICLE NO.FBN 3407B AND VEHICL NO. YN5530J AT CENTRAL EXPRESSWAY ON 08 MAY 2022 AT 19:30 HRS-NOTICE

FOR PRE REPAIR INSPECTION

CAUTION: This Email is from an EXTERNAL source. Ensure you trust this sender (Email) before replying or clicking on any links and open attachments.

Our ref: FBC 3407B;

Your ref YN5530J

Dear Sirs,

CUSTOMER: NOOR AZMAN BIN MOENIR

ACCIDENT INVOLVING VEHICLE NO.FBN 3407B AND VEHICLE NO. YN5530J AT CENTRAL EXPRESSWAY ON 08 MAY 2022 AT 19:30 HRS

NOTICE FOR PRE REPAIR INSPECTION

We act for **NOOR AZMAN BIN MOENIR** ("our client"), owner and rider of motorcycle no. **FBC 3407B**, in her claim for personal injuries, property damage and consequential loss and expense as a result of the above captioned road traffic accident involving your insured driver of motor car no.

YN 5530J.

As a result of the accident, our client was injured and our client's motorcycle was damaged and she suffered other consequential losses.

Please let us know within 2 working days upon receipt of this notice whether you intend to conduct a pre-repair survey of our client's motorcycle. In the event that you do not respond within the stipulated timeline, our client will proceed to repair the motorcycle without further reference to you.

If you wish to conduct a survey, please liaise with Mr Erzat at 9898 3441 or Ms Hidayah at 89521184 failing which, we will proceed accordingly.			
Please note the said mo	otorcycle can be inspected at:		
Name of workshop:	Erzat Lee Motor Trading Pte Ltd		
Address: Synergy @	Kaki Bukit 25, #03-37 Kaki Bukit Rd 4, Singapore 417800		
Contact details:	Mr Erzat at Mobile no. 9898 3441		
	Ms Hidayah at 89521184		
Best Regards,			
Nur Hidayah			
Administrative Executive			
Erzat Lee Motor Trad	ling Pte Ltd		
Synergy@KB 23			
Kaki Bukit Road 4			
#01-19 Level 2 Singa	pore 417801		
E: <u>Hidayah@erzatleemotor.com</u>			
delete it and notify ι	dential and may also be privileged. If you are not the intended recipient, please us immediately; you should not copy or use it for any purpose, nor disclose its er person. Thank you]		