

Our Ref: GBJ8390U220418

Date: 03/07/2022

Your Ref:

AIG Asia Pacific Insurance Pte Ltd
No. 78 Shenton Way #07-16
AIG Building
Singapore 079120

Attn: Motor Claims Department

Dear Sir / Madam

Traffic Accident Along Sims Avenue
Involving GBJ8390U **and** SLJ2260H **On** 18/04/2022

We/I, **Goldbell Leasing Pte Ltd** (NRIC / ROC No: 199001196N), the registered owners of m/vehicle - GBJ8390U at all material times of the above accident. Our/my vehicle was surveyed by “AIG Asia” authorized appraiser and we/I based our/my claims on his recommendation for S\$ 1,300-00 being the repair for 03 Days (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle SLJ2260H when the same was involved in the aforesaid accident with our/my m/vehicle - GBJ8390U.

We/I whereby you are the insurers of m/vehicle SLJ2260H and the driver/owner was caused solely by the negligence of your insured and as a result there of our / my m/vehicle - GBJ8390U has suffered loss and damage as follows:

Cost of repairs	S\$	<u>1,300-00</u>
LOU for pre-repair notice 02 days @ S\$ <u>80-00</u> [2982 cc]		<u>160-00</u>
LOU Fee for <u>03</u> days @S\$ <u>80-00</u> [2982 cc]		<u>240-00</u>
Rental Fee Invoice No: _____		_____
GIA / LTA search fee		_____
Towing Fee (Cash Sale No _____)		_____
Survey Fee		_____
Total Amount	S\$	<u>1,700-00</u>

We/I enclose herewith copies of the supporting documents for vehicle no. GBJ8390U as follows:-

- (i) Motor Accident Report & Documents;
- (ii) Repair Invoices;

Kindly look into the matter and let us/me hear from you on the settlement of our/my claims as soon as possible.

Please remit us/me your settlement sum in favor of M/s Liu’s Brother Auto Engineering Workshop. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,

f-----

The owner of m/vehicle GBJ8390U
Messers Goldbell Leasing Pte Ltd
cc. Liu’s Bro Auto Engineering Workshop



FINAL BILL

Name: AIG Asia Pacific Insurance Pte Ltd
 Address: Motor Claims Department
 78 Shenton Way #07-16
 AIG Building Singapore 079120

Ref Date: 03/07/2022
 Ref No: GBJ8390U220418
 Vehicle No: GBJ8390U
 Model / Make: Toyota Hiace
 Van Turbo 5DR MT

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Front	Bumper	\$ 796.80	1	\$ 796.80		\$ -
2		Bumper Clips 1 set	\$ 50.00	1	\$ 50.00	SN	\$ -
3		Bumper Bracket Lh	\$ 178.00	1	\$ 178.00		\$ -
4		Step Garnish	\$ 372.80	1	\$ 372.80		\$ -
5		Step Garnish Clips 1 set	\$ 30.00	1	\$ 30.00	SN	\$ -
6		Head Lamp	\$ 930.70	1	\$ 930.70		\$ -
7		Head Lamp Clip 1 set	\$ 65.00	1	\$ 65.00	SN	\$ -
8		Head Lamp Bracket	\$ 116.30	1	\$ 116.30	SN	\$ -
9		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc			\$ 400.00		\$ -
10		To putty & spray painting & including touch up paint on accident affected areas			\$ 300.00		\$ -
11		To apply Rust Proofing , reseal tuff-coating treatment on accident area			\$ 40.00		\$ -
12		To check all wiring & electrical component for proper function			\$ 40.00		\$ -
					\$ -		

Total Parts & Labour of estimate for damaged vehicle

\$ 3,319.60

Total amount in Lumpsum Basis for repaired vehicle

\$ 1,300.00

SDL One Thousand Three Hundred Only



Liu's Bro Auto Engrg Wks