

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22005833/APA3Q2**Date:** 24/11/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070132678
Claimant Vehicle No :	GBL3718G	Insured Vehicle No :	SMV5377K
Date of Loss:	13/06/2022	Nature of Claim:	TP
		Claim No:	9633366448SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBL3718G		
Make & Model:	NISSAN NV200, 1.6 MT PETROL (A)	Engine No:	HR16189325D
Reg. Date:	30/06/2021 (Man. Year: 2021)	Chassis No:	JN1YAAM20Z0002250
Colour:	Orange	Odometer:	22161 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	165/80 R14	Rear Tyre Size:	165/80 R14
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,705.06	4,636.20	3,068.86	39.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,630.00	1,610.00	1,020.00	38.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,335.06	6,246.20	4,088.86	39.56
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	10,335.06	5,000.00	5,335.06	51.62
+ GST 7.00/7.00% (S\$)	723.45	350.00	373.45	51.62
Nett Amount (S\$)	11,058.51	5,350.00	5,708.51	51.62
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
Nett Liability (S\$)		6,050.00		
Global Sum Settlement (S\$)		6,050.00		

INSPECTION

Date of Assignment:	15/06/2022		
Date Inspected:	15/06/2022	Inspected At:	J-mart Motor Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-578 Singapore 539186
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,978.00 FN	*1,835.00 FN
2	1		*TAILGATE LOCK	Damaged	332.00 FN	*332.00 FN
3	1		*TAILGATE W/STRIP	Cut	118.00 FN	*118.00 FN
4	1		*NISSAN EMBLEM	Necessary	97.00 FN	*97.00 FN
5	1		*NV 200 EMBLEM	Necessary	145.00 FN	*145.00 FN
6	1		*VANETTE EMBLEM	Necessary	97.00 FN	*97.00 FN
7	1		*TAILGATE OUTER GARNISH	Not Necessary	366.00 FN	*- FN
8	1		*REAR BUMPER	Deformed	663.00 FN	*481.00 FN
9	2		*REAR BUMPER RETAINERS	Necessary	98.00 FN	*98.00 FN
10	1		*REAR BUMPER SPONGE	Cracked	119.00 FN	*119.00 FN
11	8		*REAR BUMPER CLIPS	Necessary	44.00 FN	*44.00 FN
12	1		*END PANEL	Dented	368.00 FN	*368.00 FN
13	1		*END PANEL INNER GARNISH	Deformed	97.00 FN	*97.00 FN
14	5		*END PANEL INNER GARNISH CLIPS	Necessary	27.50 FN	*10.00 FN
15	1		*TAILLAMP	N/S Cracked	554.00 FN	*277.00 FN
16	1		*BODY PANEL	Repair	1,979.90 FN	*- FN
17	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
18	1		*REAR W/SCREEN GUM	Necessary	50.00 FS	*50.00 FS
19	1		*REAR W/SCREEN SEAL	Necessary	30.00 FS	*30.00 FS
20	1		*COMPANY LOGO	Necessary	1,000.00 FS	*650.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	8,413.40	5,048.00
- Nett Item Discount on N Items 10.00/10.00% (S\$)	708.34	411.80
Total Parts (S\$)	7,705.06	4,636.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING	New	1,200.00	600.00
3	WIRING	New	30.00	30.00
4	TRANSFER TAILGATE FITTING	New	80.00	60.00
5	REMOVE & REFIT REAR W/SCREEN	New	120.00	120.00
Gross Labour Cost (\$)			2,630.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >