

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Cecilia Lee

Date: 20 Jun 2022

Preliminary Advice

Vehicle No	: SMP4721M	Accident Date	: 15/06/2022
Make	: TOYOTA NOAH HYBRID	Policy No.	: DMHCSNW00007942100
Assignment Date	: 20/06/2022	Excess	: S\$1,250.00
Date of Inspection	: 20/06/2022	Est. Duration of Repair	: 10
Inspection At	: DING AUTO PTE LTD (HQ) 176 SIN MING DRIVE #04-06, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,428.91
Revised Amount	:S\$	6,288.91
Check Items (Estimated)	:S\$	5,888.00
Total	:S\$	12,176.91
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	130,000.00
COE / PARF Rebate	:S\$	50,633.00
Salvage Value	:S\$	
Margin for Repair	:S\$	79,367.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Repair on part by part