

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22005835/KQY3E2

Date: 27/07/2022

REFERENCE

Insured/Claimant: Autovill Export and Lease Policy No: DMCVSN00094542100

Date of Loss: 14/06/2022

Nature of Claim: OD

Claim No: SNM22D204152/C01/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG585T**

Make & Model: NISSAN NV200, 1.5 MT (M)

Reg. Date: 30/05/2017 (Man. Year: 2016)

Colour: Silver

Engine Capacity: 1461 cc

Market Value/New Car Price: S\$43,000.00

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: K9KC400D056824

Chassis No: VSKYBAM20Z0143767

Odometer: 141298 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14

Front Left Side: ULTIMAX 3 mm

Front Right Side: Goodyear 2 mm

Rear Tyre Size: 175/70 R14

Rear Left Side: MARSWAY 2 mm

Rear Right Side: MARSWAY 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,350.00	3,400.00	2,950.00	46.46
Miscellaneous Items	315.00	280.00	35.00	11.11
Labour	621.60	222.60	399.00	64.19
Paintwork Labour	542.55	367.95	174.60	32.18
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,829.15	4,270.55	3,558.60	45.45
Approved Total (Overridden) (S\$)		3,100.00		
- Excess (S\$)	0.00	2,000.00	-2,000.00	
(S\$)	7,829.15	1,100.00	6,729.15	85.95
+ GST 7.00/7.00% (S\$)	548.04	77.00	471.04	85.95
Nett Amount (S\$)	8,377.19	1,177.00	7,200.19	85.95

INSPECTION

Date of Assignment: 20/06/2022 Present Location:

S & H Motor Pte Ltd (Sin Ming)

Date Inspected: 20/06/2022 Inspected At:

S & H Motor Pte Ltd (Sin Ming)

160 Sin Ming Drive #07-02, Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	misc	315.00	280.00
			Sub Total (\$\$)	280.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Labour for paintwork	New	542.55	367.95
<u>Labour Items</u>				
2	Labour for panel/mechanical	New	621.60	222.60
			Gross Labour Cost (\$\$)	590.55

Report was unsubmitted during this print-out.

< END OF ESTIMATES >