#### Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

Tokio Marine Insurance Singapore From: LKK Auto Consultants Pte Ltd Ltd

51 Ubi Ave 1 #01-25 20 McCallum Street Paya Ubi Industrial Park #09-01 Tokio Marine Centre

Singapore 408933 Singapore 069046

Date: 28 Jun 2022 Attn: Fiona Gan Bee Song

## **Preliminary Advice**

: SNC4750K Insured

Vehicle No

TP Vehicle Accident Date : SHC2045Y : 16/06/2022

No

Make : HYUNDAI IONIQ HYBRID Assignment Date: 20/06/2022

Date of : 20/06/2022 Est. Duration of : 3

Inspection Repair

Inspection At: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

**59 LOYANG DRIVE** SINGAPORE 508969

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 1,596.16 **Revised Amount** :S\$ 1,397.12 Check Items (Estimated) :S\$ 0.00 Total :S\$ 1,397.12

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

### Remarks

(	) The vehicle is repairable at our adjusted amount. We have also confirmed
	excess and policy coverage. Kindly let us have your authorisation.

- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.