



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (S) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807			Ref: CS/MSG22005847/Eqy3e2	
			Date: 27/07/2022	
			Code: MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	PB 555R
	Policy No.		Coverage (\$)	0.00
	Claim No.	272529	Excess (\$)	0.00
	Assign From	ONG SHU XIANG	Assign Date	17/06/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA REGIUS ACE	c.c	2754
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	GDH2011031266	Colour	SILVER
	Odometer	28667 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	GOODYEAR	5 mm
	L/H Front Tyre	195 R15C	GOODYEAR	5 mm
	R/H Rear Tyre	195 R15C	GOODYEAR	5 mm
	L/H Rear Tyre	195 R15C	GOODYEAR	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/03/2022	Inspection Date	20/06/2022
	Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	