



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ECICS LTD 10 EUNOS ROAD 8 SINGAPORE POST CENTRE #09-04A SINGAPORE 408600		Ref: CS/ICS22005855/Vvy3 Date: 20/06/2022 Code: ICS	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMG 4222J	Veh. Inspected	GBH 2858M
Policy No.		Coverage (\$)	0.00
Claim No.	DMCF2200096H/02/JT	Excess (\$)	0.00
Assign From	JARIUS TAN	Assign Date	20/06/2022
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	15/06/2022	Inspection Date	22/06/2022
Survey held at	HANG KHIANG MOTOR WORKSHOP BLK 3012 BEDOK INDUSTRIAL PARK E, #01-2042 BEDOK NORTH AVE 4, SINGAPORE 489978.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			