

ASS. REC. BY:

REF: SMO/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: 851k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

11/26

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Job No: SGN1644D Yr Regn: 11.06

M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or WagonMake: Toy Erring C.C. 2362Colour: h. Black A/C: Insured / Std / NI / NASp. Reading: 261284 T/Radio: Insured / Std / NI / NA

Eng No: _____

Chassis: ACR50.0006494Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD / R/Rim or

Tyre Size: F: hiz 215/65R17Continental

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 4 mmR/Bal: 5 mmL/Bal: 4 mmL/Bal: 5 mmD.O.A. 17/6/22D.O.I. 21/6/2022

Survey held at _____

Des. of Damages: FR Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 W/cep said will try bump bump, maybe part by part.

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

Site Insp (\$)

) S + RS. \$

☐

Interview (\$)

) Fee

☐

Tech Invs (\$)

) Other

☐

Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$)

L.T.A.

來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0029628
Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#03-03 Singapore Land Tower
Singapore 048623

Page 1 of 4
Your ref. D21MTPV01015617
Job No. 72777
Our ref. 22.06.28
Payment
Date 20/6/2022

Attn

Vehicle No SGN 1644D
Vehicle Model : Toyota Estima
Accident on ... 17/6/2022

Not Authorized
LI Pay 8
Recovery After Pain
Today

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Bonnet	200.00		<i>Ry</i> 200.00 ✓
1.00	Pc	Bonnet hinge LH	25.00		<i>Dir</i> 25.00 ✓
1.00	Pc	Bonnet hinge RH	25.00		<i>Dir</i> 25.00 ✓
1.00	Pc	Bonnet lock	45.00		<i>Ry</i> 45.00 ✓
1.00	Pc	Bonnet insulation	100.00		<i>Sm</i> 100.00 X
1.00	Pc	Front bumper	750.00		<i>Paul</i> 750.00 ✓
1.00	Pc	Front bumper centre grille	60.00		<i>CNA</i> 60.00 ✓
1.00	Pc	Front bumper top beam	50.00		<i>Ry</i> 50.00 ✓
1.00	Pc	Front bumper sponge	38.00		<i>CNA</i> 38.00 ✓
1.00	Pc	Front bumper rubber stopper LH	5.00		<i>Dir</i> 5.00 ✓
1.00	Pc	Front bumper rubber stopper RH	5.00		<i>Dir</i> 5.00 ✓
5.00	Pcs	Front bumper clips	1.50		<i>Ry</i> 7.50 ✓
1.00	Pc	Front fog lamp LH	115.00		<i>Sm</i> 115.00 X
1.00	Pc	Front fog lamp RH	115.00		<i>Sm</i> 115.00 X
1.00	Pc	Front fog lamp bulb RH	18.00		<i>Est</i> 18.00 X
1.00	Pc	Front headlamp LH	700.00		<i>Bro</i> 700.00 ✓
1.00	Pc	Front headlamp RH	700.00		<i>Bro</i> 700.00 ✓
1.00	Pc	Front signal lamp bulb LH	6.00		6.00 7

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

來發 (明記) 摩多有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0029628
Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#03-03 Singapore Land Tower
Singapore 048623

Page 2 of 4
Your ref. D21MTPV01015617
Job No. 72777
Our ref. 22.06.28
Payment
Date 20/6/2022

Attn

Vehicle No SGN 1644D
Vehicle Model : Toyota Estima
Accident on ... 17/6/2022

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00	Pc	Radiator grille	160.00		CM 160.00 ✓
1.00	Pc	Radiator grille logo emblem	40.00		MC 40.00 ✓
5.00	Pcs	Radiator grille clips	1.50		MC 7.50 ✓
1.00	Pc	Radiator grille top cover	90.00		CM 90.00 ✓
6.00	Pcs	Radiator grille top cover clips	2.00		MC 12.00 ✓
1.00	Pc	Front support panel (centre)	110.00		BT 110.00 ✓
1.00	Pc	Front headlamp panel LH	100.00		BT 100.00 ✓
1.00	Pc	Front headlamp panel RH	100.00		BT 100.00 ✓
1.00	Pc	Radiator	500.00		500.00 ?
1.00	Pc	Radiator cowl	110.00		110.00 ?
1.00	Pc	Radiator fan blade	60.00		60.00 ?
1.00	Pc	Radiator fan motor	170.00		170.00 ?
1.00		Radiator coolant - 4 litres	22.00		MC 22.00 ✓
1.00	Pc	Washer tank	60.00		60.00 ?
1.00	Pc	Aircon condenser	380.00		MC 380.00 ✓
1.00	Pc	Aircon fan blade	75.00		75.00 ?
1.00	Pc	Aircon fan motor	170.00		170.00 ?
1.00	Pc	Battery top bracket	25.00		BT 25.00 ✓
1.00	Pc	ECU	1,200.00		MC 1,200.00 X

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0029628
Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#03-03 Singapore Land Tower
Singapore 048623

Page 3 of 4
Your ref. D21MTPV01015617
Job No. 72777
Our ref 22.06.28
Payment
Date 20/6/2022

Attn

Vehicle No SGN 1644D
Vehicle Model : Toyota Estima
Accident on ... 17/6/2022

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Total amount of parts supplied - S\$6,356.00					
1.00		10% of parts supplied:	635.60		635.60
		Special nett item:			
1.00	Pc	Front number plate	35.00		<i>R</i> 35.00 ✓
		Labour & Misc:			
1.00		To check/erase fault codes	80.00		80.00 ✓
1.00		To remove + renew aircon condenser + refill gas	150.00		150.00 <i>100%</i>
1.00		To reprogramme ECU	350.00		350.00 <i>?</i>
1.00		To straighten front body including cutting and welding; to renew of parts	650.00		650.00 <i>600%</i>

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0029628
Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#03-03 Singapore Land Tower
Singapore 048623

Page 4 of 4
Your ref. D21MTPV01015617
Job No. 72777
Our ref. 22.06.28
Payment
Date 20/6/2022

Attn

Vehicle No SGN 1644D
Vehicle Model : Toyota Estima
Accident on ... 17/6/2022

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To spray paint (including blend front fender LH & RH)	800.00		800.00 <i>71d</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub-Total 9,056.60
GST 7.00% 633.96
Total S\$ 9,690.56

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	18/06/2022 13:26 (SGT)
Date of Accident	17/06/2022 18:30 (SGT)
Exact Location of Accident	Balestier Rd, Singapore
Additional Location Information	Balestier Road towards CTE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGN1644D
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	Chin Guan Kiat
NRIC No	SXXXX140B
Email Address	terry@strom.com.sg
Mobile Phone No	(Phone) +65-97907567
Alternative Phone No	+65-97907567

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Estima
Variant	Aeras 2.4A
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	2362

INSURANCE COMPANY

Name of Insurance Company	Sompo Insurance Singapore Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	D21MTPV01015617
Cover Note Number	-

DRIVER

Name of Driver	Chin Guan Kiat
NRIC No	SXXXX140B

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law, in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &
Time 18 JUN 2022


Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

Balestier Road towards CTE

3GN 1644D
GBG 5773J
3KD 5676Y



OneMotoring

PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Singapore NRIC

140B

Vehicle Details

Vehicle No.:

SGN1644D

Vehicle to be Exported:

No

Intended Deregistration Date:

18 Jun 2022

Vehicle Make:

TOYOTA

Vehicle Model:

ESTIMA AERAS 2.4 A

Primary Colour:

Black

Manufacturing Year:

2006

Engine No.:

2AZC061859

Chassis No.:

ACR500006494

Maximum Power Output:

125.0 kW (167 bhp)

Open Market Value:

\$31,948.00

Original Registration Date:

10 Nov 2006

First Registration Date:

10 Nov 2006

Transfer Count:

2

Actual ARF Paid:

\$33,399.00

Intended PARF Rebate Details

PARF Eligibility:

Forfeited

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

09 Nov 2026

COE Category:

E - Open Category

COE Period(Years):

10

PQP Paid:

\$56,053.00

COE Rebate Amount:

\$24,625.00

Total Rebate Amount:

\$24,625.00

The information contained herein is correct as at 18 Jun 2022

OK