



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2206196

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 05/10/2022
Reference CS3/GRB22001847/Vqy3e-
1
Code GRB

PROFESSIONAL SERVICE FEE

Vehicle No. FBS 4495E
Insured Veh. SLG 3585E
Claim No. MFL2021D0002065
Policy No. D21MFL0000447
Accident Date 09/05/2021
Inspection Date 28/02/2022

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Less: Pre-Repair Survey Fee (Invoice.AC2201439 dated 16/03/2022)	-120.00
Subtotal	230.00
GST (7%)	16.10
Grand Total	246.10

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM