

FASTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6 #01-48 Autobay
 Singapore 417883
 Tel No: 67452063/ 67467158 Fax No: 67458520
 Tax Reg No : 200006262D

not authorized
 LLL
 21/06/22
 1/5 @ 5000 /
 5 days.

VEHICLE No: SMW 1564H

1PC	BOOTLID	∞/but	2023.20	\$2,223.20	—
1PC	BOOTLID REAR LOGO	11		\$75.80	X
1PC	BOOTLID 'AVANTE' EMBLEM	neu		\$42.00	—
1PC	BOOTLID 'ELITE' EMBLEM	neu		\$65.00	—
1PC	BOOTLID REFLECTOR CENTRE	11		\$1,162.20	X
1PC	BOOTLID INNER LOCK	but		\$148.00	✓
1PC	BOOTLID LOCK SWITCH	11		\$101.40	X
1PC	BOOTLID WEATHERSTRIP	11	108.30	\$166.00	✓
1PC	BOOTLID INNER TRIM	11		\$265.00	X
2PCS	BOOTLID HINGES @\$145.00	11		\$290.00	X
1PC	BOOTLID OUTER TOP GARNISH	11		\$1,125.80	X
1PC	BOOTLID OUTER TOP GARNISH INNER BRACKET	11		\$250.00	X
2PCS	BOOTLID OUTER TOP GARNISH INNER SIDE BRACKETS @\$50.00	11		\$100.00	X
1PC	BOOTLID OUTER TOP SPOILER INNER [BLACK]	11		\$450.00	X
1SET	BOOTLID REVERSE CAMERA	11		\$745.00	X
1PC	REAR BUMPER	mid	470.80	\$481.00	—
1PC	REAR BUMPER LOWER	one		\$640.60	—
1PC	REAR BUMPER CENTRE LAMP	one	201.50	\$280.00	—
2PCS	REAR BUMPER SIDE RETAINERS @\$65.00	11		\$130.00	X
2PCS	REAR BUMPER REFLECTORS @\$ 58.20	11		\$116.40	X
1PC	REAR BUMPER SPONGE	NF		\$245.00	X
1PC	REAR BUMPER REINFORCEMENT	∞	294.80	\$329.00	—
2PCS	REAR BUMPER REINFORCEMENT BRACKETS @\$151.00	11		\$302.00	X
2PCS	REAR BUMPER REINFORCEMENT TOP BRACKETS @\$25.00	11		\$50.00	—
3PCS	REAR BUMPER REINFORCEMENT LOWER BRACKETS @\$25.00	11		\$75.00	—
4PCS	REAR BUMPER PDC SENSORS @\$169.20	shrub		\$676.80	✓
1SET	REAR BUMPER PDC SENSOR WIRE	11		\$236.10	X
1PC	REAR BUMPER UNDER COVER	11		\$68.00	X
1SET	REAR BUMPER CLIPS	11		\$50.00	—
1PC	REAR END PANEL	∞	454.60	\$537.00	—
1PC	REAR END PANEL TOP GARNISH	11		\$188.90	X
2PCS	TAILLAMPS @\$659.00	11		\$1,318.00	X
2PCS	TAILLAMP HOUSING PANELS @\$250.00	11		\$500.00	X
1PC	REAR EXHAUST	11		\$981.00	X
1PC	REAR EXHAUST HEAT SHIELD	11		\$145.00	X
1PC	REAR FLOOR PANEL	11		\$1,215.00	X
1PC	REAR FLOOR PANEL TOP BOARD	11		\$355.00	X
1PC	REAR WINDSCREEN MOULDING	11		\$165.00	X
				\$16,294.20	

S.NETT

(202)

1300.6
 202
 210.48
 980
 1980
 6310.48
 202
 5048

1PC	REAR WINDSCREEN SEALANT	11	\$50.00	X
1PC	REAR WINDSCREEN INNER SEAL	11	\$50.00	X
1PC	REAR END PANEL SEALANT	11	\$50.00	✓
1SET	REAR FLOOR PANEL INSULATOR	11	\$300.00	X
1SET	BOOTLID INNER TRIM CLIPS	11	\$50.00	X
1PC	REAR LICENCE PLATE	3mf	\$50.00	40

5/10

	TO CHECK WIRING		\$50.00	30
	TO DISMANTLE & REPLACED REAR REVERSE SENSOR		\$80.00	50
	TO TRANSFER BOOTLID MECHANISM		\$100.00	60
	TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY		\$120.00	80
	TO RESET & DIAGNOSTIC BLIND SPOT SENSOR	11	\$500.00	X
	TO DISMANTLE & REFIX REAR EXHAUST	11	\$100.00	X
	TO DISMANTLE & REFIX FUEL TANK	11	\$80.00	X
	TO CONDUCT CHASSIS ALIGNMENT	11	\$380.00	X
	TO DISMANTLE & REFIX REAR WINDSCREEN	11	\$150.00	X
	TO SPRAY RUST PROOFING		\$180.00	60
	LABOUR FOR PANEL BEATING & REPLACED PARTS		\$2,200.00	800
	TO PUTTY & SPRAY PAINTING		\$1,800.00	900
	TOTAL		\$22,584.20	

Open Market Value:	\$21,718.00
Original Registration Date:	04 Nov 2020
First Registration Date:	04 Nov 2020
Transfer Count:	
Actual ARF Paid:	\$12,406.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Nov 2030
PARF Rebate Amount:	\$9,304.00
Intended COE Rebate Details	
COE Expiry Date:	03 Nov 2030
COE Category:	
COE Period (Years):	
QP Paid:	
COE Rebate Amount:	
Total Rebate Amount:	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2. 5300-6
202
4240-48
90
1980
6310-48
202
8048