

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

21-Jun-22

Our ref : TP/5133/22

Ng Cheng Kwee

TP AXA
Gulian.

JM6CW107160124950

RE : estimate cost for vehicle no : SKA 6823S

1 pc	rear bumper	Dehid
1 pc	rh taillamp	cruc
1 pc	rear rh fender	Regr
1 pc	rear bumper rh retainer	re
8 pcs	rear bumper clips	re
1 pc	rear bumper rh side garnish	horn
1 pc	rerar rh air duct	Dehid

\$

1,670.00	862
780.00	602
976.00	+
70.00	✓
40.00	30
170.00	95
110.00	58.
3,816.00	

1817
1453.60

1 pc rear rh rim *ad*
Panel beating.
Spray painting.
Wiring.

400.00	snett	350
600.00	400	
600.00	400	
30.00	✓	
5,446.00		
381.22		
5,827.22		

1180

Plus 7% GST

SD : five thousand eight hundred twenty-seven & cents twenty-two only.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
w/s 22/06/22
04 Pays.
total: 2633.60
L/S 2.1K.