



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |   |   |                |
|--|--|---|---|----------------|
| AXA INSURANCE PTE LTD<br>8 SHENTON WAY #24-01 AXA TOWER<br>SINGAPORE 068811<br>ATTN: ONG KIAN THENG DERICK |  |   | Ref: CS/ASM22005892/Vqy3e2<br>Date: 17/01/2023<br>Code: ASM |                |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |  |   |   |                |
|  | <b>Insured Veh.</b>  | SHC 5829H   | <b>Veh. Inspected</b>                                       | SDZ 7755A      |
|  | <b>Policy No.</b>  | VFX/P2413997  | <b>Coverage (\$)</b>  | 0.00           |
|  | <b>Claim No.</b>   | S2M044ON  | <b>Excess (\$)</b>  | 0.00           |
|  | <b>Assign From</b>   | ONG KIAN THENG DERICK   | <b>Assign Date</b>  | 21/06/2022     |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |   |   |                |
|  | <b>Make &amp; Model</b>  | TOYOTA ALTIS 1.6  | <b>c.c</b>  | 1598           |
|  | <b>Engine No.</b>  | HIDDEN  | <b>Year of Reg.</b>   | 2008           |
|  | <b>Chassis No.</b>   | MR053ZEE106109008   | <b>Colour</b>   | SILVER         |
|  | <b>Odometer</b>  | 166767 KM   | <b>Steering</b>   | IN ORDER       |
|  | <b>Brakes</b>  | IN ORDER  | <b>Modification</b>   | SPORTS RIM     |
|  | <b>General</b>   | GOOD  |   |                |
| <b>3. Conditions of Tyres</b>  |  |   |   |                |
|  |  | <b>Size</b>   | <b>Make</b>   | <b>Balance</b> |
|  | <b>R/H Front Tyre</b>  | 195/65 R15  | MICHELIN  | 5 mm           |
|  | <b>L/H Front Tyre</b>  | 195/65 R15  | MICHELIN  | 5 mm           |
|  | <b>R/H Rear Tyre</b>   | 195/65 R15  | MICHELIN  | 5 mm           |
|  | <b>L/H Rear Tyre</b>   | 195/65 R15  | MICHELIN  | 5 mm           |
| <b>4. Description of Damages</b>   |  |   |   |                |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.   |   |   |                |
| <b>5. General Information</b>  |  |   |   |                |
|  | <b>Accident Date</b>   | 20/06/2022  | <b>Inspection Date</b>                                      | 22/06/2022     |
|  | <b>Survey held at</b>  | GALAXY AUTO CARE PTE LTD<br>13 KAKI BUKIT ROAD 4 #01-23 BARTLEY BIZ CENTRE SINGAPORE 417807 |   |                |
| <b>5a. Remarks</b>   |  |   |   |                |
|  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |   |                |
| <b>5b. Estimate Days of Repair</b>   |  |   |   |                |
|  | ESTIMATED NORMAL PERIOD FOR REPAIR:  |   | <b>6 Working Days</b>                                       |                |