

(08/11/13)

ASS. REC. BY:

REF:

C8/ASM22005892/Vqy3

ASSIGNMENT

COE Expiry Date = 29/5/2028

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$47,000

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SDZ 7755A Yr Regn: 30/5/2008

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Artis 1.6 c.c.

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 166767 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053 ZEE1 06109008

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal: 5 mm R/Bal: 5 mm

L/Bal: 5 mm L/Bal: 5 mm

D.O.A: 20/6/2022 D.O.I: 22/6/2022

Survey held at Galaxy Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

N.V. - \$25,700

1/11 - No re-survey photo.

Finalised LS \$3050, 6 days (Red \$3444.05, 53%)

Date/Time, File Pass to?

1/16/11 tyger

Date/Time, File Return to?

2)

☐: Prel. Report☐: Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: Smart Claims - TP

Lump Sum / I.B.I: (\$ 3050)



GALAXY AUTO CARE PTE LTD

13 Kaki Bukit Road 4 #01-23 Bartley Biz Centre Singapore 417807

Tel: 9010 8488 Fax: 9010 8488

Email: galaxyautosg@gmail.com

22 June 2022

REG NO. : SDZ 7755 A

MAKE/MODEL : TOYOTA COROLLA ALTIS

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(S\$)
<u>LIST ITEMS</u>		
1	Rear boot lid	\$ 878.20 ✓ MT
1	Rear boot lamp	\$ 181.50 ✓
1	Rear boot inner lock	\$ 166.75 ✓
1	Rear boot logo	\$ 58.50 ✓ n/c
1	Rear boot weatherstrip	\$ 165.60 ✓
1	Rear boot "COROLLA" emblem	\$ 55.30 ✓ n/c
1	Rear boot "ALTIS" emblem	\$ 52.50 ✓ n/c
1	Rear boot "1.6" emblem	\$ 48.40 ✓ n/c
1	Rear taillamp -RH	\$ 410.95 ✓
1	Rear taillamp lower bracket	\$ 85.50 ✓
1	Rear end panel	\$ 762.60 ✓
1	Rear end panel inner garnish	\$ 192.50 ✓
1	Rear bumper	\$ 580.60 ✓ lub
1	Rear bumper reflector	\$ 75.50 ✓ C/A
2	Rear bumper side retainers	\$ 131.00 ✓ n/c
		\$ 3,845.40
	Less 25%	\$ 961.35
		\$ 2,884.05

SPECIAL NETT ITEMS

1	Rear bumper clip (1 set)	\$	50.00	300cc
1	Rear reverse sensor (1 set)	\$	350.00	100cc
		\$	400.00	

S/NO. LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	110
2	To remove and refit inner garnishes.	\$	150.00	50
3	To remove and refit rear reverse sensor.	\$	150.00	30
4	To transfer boot lid mechanism and wiring assembly.	\$	80.00	40
5	To apply undercoating.	\$	150.00	30
6	Panel beating.	\$	1,400.00	400
7	To re-spray painting on the affected areas.	\$	1,200.00	400
		\$	3,210.00	

GRAND TOTAL :

\$ 6,494.05

> Back to OneMotoring

D.O.A. : 20/6/2023
Bal. : 5 yrs 11.3 mths.
M.V. : \$47,000

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	421B
Vehicle Details	
Vehicle No.:	SDZ7755A
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Nov 2022
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	3ZZ4767110
Chassis No.:	MR053ZEE106109008
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,777.00
Original Registration Date:	30 May 2008
First Registration Date:	30 May 2008
Transfer Count:	3
Actual ARF Paid:	\$16,777.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 May 2028
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$38,192.00
COE Rebate Amount:	\$21,282.00
Total Rebate Amount:	\$21,282.00

The information contained herein is correct as at 01 Nov 2022

OK

9,180
9,050
8,770
8,220