

MY CAR CONSULTANT PTE LTD
(Co Reg. No. 201605878Z)
60 JALAN LAM HUAT, CARROS CENTRE
#05-68 SINGAPORE 737869

NOT Whorah
Repairing Bg pain
1/12/22 @ 1950h 4 days

TO	: SOMPO	DATE	: 21-Jun-22
ATTENTION	: MOTOR CLAIMS DEPT		: T/P CLAIM
OWNER'S PARTICULAR		VEHICLE DETAILS	
NAME	:	VEHICLE NO	: SNF1369H
ADDRESS	:	MODEL	: TOYOTA ALPHARD

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER 1605. m/crm	1	\$ 1,790.00	\$ 1,790.00
2	REAR BUMPER SIDE RETAINER RH	1	\$ 85.00	\$ 85.00
3	REAR FENDER RH	1	\$ 798.00	\$ 798.00
4	REAR SLIDING DOOR RH	1	\$ 2,110.00	\$ 2,110.00
TOTAL PRICE				\$ 4,783.00
LESS 25%				\$ 1,195.75
SUB TOTAL PRICE				\$ 3,587.25

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS	1	\$ 65.00	\$ 65.00
TOTAL				\$ 65.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	APPROVED
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 600.00	500
2	TO SPRAY PAINT AFFECTED AREA	\$ 800.00	600
3	TUFF COAT	\$ 250.00	X
4	REMOVE & REFIX REVERSE SENSOR & DISTANCE SETTING	\$ 80.00	50

TOTAL \$ 1,730.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 3,652.25