

Huey Yon (LKKAuto)

From: Huey Yon (LKKAuto)
Sent: Monday, 27 March 2023 10:24 AM
To: Kelvin Chew
Cc: SUR
Subject: RE: SKL 8302H OD AIS

Dear Kelvin,

Without prejudice

We will be advising our principal a cost of repair of \$31,548.25 before excess \$700.00 and GST with 5 days of repair , subject to their approval.

Best Regards,
Huey Yon | Case Handler
LKK Auto Consultants
phone: 6256-3561 | email: hueyyon@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kelvin Chew <kelvin.chew@firstautoworks.com.sg>
Sent: Thursday, February 23, 2023 7:31 PM
To: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Re: SKL 8302H OD AIS

Dear Huey Yon,

Attach is finalise report, resurveyed estimate & after repair photo.
Part by part \$31548.25 before excess \$700 & 5 working days.
Kindly please check & confirm with me.
Thanks.

from,
kelvin
8292 5595

From: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>
Sent: 14 December 2022 10:06
To: Kelvin Chew <kelvin.chew@firstautoworks.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: SKL 8302H OD AIS

Dear Sir/Mdm,

Please proceed the supplementary as attached with our surveyor marking.

Best Regards,

Huey Yon | case handler
LKK Auto Consultants Pte.Ltd.
Phone: 6256-3561 Fax: 62564315 email: hueyyon@lkkauto.com

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Friday, 24 June 2022 4:39 PM
To: kelvin.chew@firstautoworks.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: Fw: SKL 8302H OD AIS

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKL 8302H** (Excess \$700/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: [6256-3561](tel:6256-3561) | email: denisetay@lkkauto.com | fax: [6256-4315](tel:6256-4315)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)