



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL

INV No. AC2204167

50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWER
SINGAPORE 048623

INV Date 06/07/2022
Reference CS3/SMO22005913/Ucy3e2
Code SMO

PROFESSIONAL SERVICE FEE

Vehicle No. FV 8082Z

Insured Veh. GBF 5651H

Claim No. CMTD2202132/AGC

Policy No.

Accident Date 16/06/2022

Inspection Date 24/06/2022

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 27.06.2022)	10.00
Repaired vehicle before return to claimant as per NIMA Protocol (Photo taking + Transport on 29.06.2022)	10.00
Subtotal	120.00
GST (7%)	8.40
Grand Total	128.40

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM