

Not Authored
1/1/2022 @ 1300h

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9046T**AAD2206-076**

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD9046T

JTDKB3FUX03076032

200303878K

TOYOTA

PRIUS

18/06/2022

SMR3785A/ ERGO.

01/11/2018

22 JUN 2022

PART	LIST
1 PANEL SUB-ASSY, FRONT DOOR, RH	\$ 1,300.70 X
1 HINGE ASSY, FRONT DOOR, LOWER RH	\$ 110.60 X
1 HINGE ASSY, FRONT DOOR, UPPER RH	\$ 97.50 X
1 TAPE, BLACK OUT, NO.1 FRT RH	\$ 13.30 X
1 TAPE, BLACK OUT, NO.2 FRT RH	\$ 43.50 X
1 TAPE, BLACK OUT, NO.3 FRT RH	\$ 26.30 X
1 WEATHERSTRIP, FRONT DOOR, RH	\$ 231.30 X
1 FENDER SUB-ASSY, FRONT LH	\$ 977.80 ✓
1 LINER, FRONT FENDER, LH	\$ 210.30 ✓
1 RIM	\$ 1,900.10 X
1 HUB CAP	\$ 211.50 X
1 ABSORBER ASSY, SHOCK, FRONT RH	\$ 472.30 X
1 KNUCKLE, STEERING, RH	\$ 663.40 X
1 ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH	\$ 760.10 X
TOTAL	\$ 1,823.20
25%	\$ 455.80
	\$ 1,367.40

Special Nett	
1 CLIP(FOR FRONT DOOR TRIM BOARD)	\$ 65.00 X
1 FRT DOOR STICKER 'TRANSCAB'	\$ 100.00 X
1 FRT DOOR ADVERTISEMENT	\$ 200.00 X
1 TYRE	\$ 350.00 X
1 FENDER LINER CLIP	\$ 65.00 ✓
TOTAL	\$ 780.00
TOTAL PARTS	\$ 2,147.40

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9046T

AAD2206-076

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	301
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	4401
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	101
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,800.00	2001
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
TOTAL	\$	4,790.00	
Over All Total	\$	6,937.40	

(PART-BY-PART) Repair Days**20 Days****2 days****LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:**