



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22005919/Tqy3m4 Date: 02/05/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 5503C	Veh. Inspected	SKL 7605R
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/06/22/2050	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	21/06/2022
2. Vehicle Particulars & Condition				
	Make & Model	AUDI Q5	c.c	1984
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	WAUZZZF7J2126597	Colour	WHITE
	Odometer	41394 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R19	BRIDGESTONE	6 mm
	L/H Front Tyre	235/55 R19	BRIDGESTONE	6 mm
	R/H Rear Tyre	235/55 R19	BRIDGESTONE	6 mm
	L/H Rear Tyre	235/55 R19	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	20/06/2022	Inspection Date	24/06/2022
	Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	