



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: CYNTHIA			Ref: CC4/ASM22005928/Epa3q2 Date: 17/04/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8037G	Veh. Inspected	SNE 8640H	
Policy No.	P2465679	Coverage (\$)	0.00	
Claim No.	S2M044L5	Excess (\$)	0.00	
Assign From		Assign Date	21/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A3	c.c	999	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WAUZZZ8V6J1055000	Colour	RED	
Odometer	44622 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	GOODYEAR	4 mm	
L/H Front Tyre	205/55 R16	GOODYEAR	4 mm	
R/H Rear Tyre	205/55 R16	GOODYEAR	4 mm	
L/H Rear Tyre	205/55 R16	GOODYEAR	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/06/2022	Inspection Date	23/06/2022	
Survey held at	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	