

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts En	Automo	^{bile} CS3/GA	l22003878/Bvy3	
	GREAT AMERICAN	N INSURANCE COMPANY		Ref:	CC0/O/H220		
	3 TEMASEK AVEN #16-01 CENTENNI SINGAPORE 03919	AL TOWER		Date:	22/04/0	22/06/2022	
				Code:	GAI		
1.	Policy Particulars :- (THIRD PARTY CLAIM)						
	Insured Veh.	SLL 146H	Veh. Inspected		SLC 9229R		
	Policy No.		Coverage (\$)		0.00		
	Claim No.	CLMOMVP000001202	Excess (\$)		0.00		
	Assign From KOH	H MING SHAO	Assign Date		20/04/0002	22/06/2022	
2.	Vehicle Particulars & Condition						
	Make & Model		c.c		0		
	Engine No.	HIDDEN	Year of Reg.				
	Chassis No.		Colour				
	Odometer	-	Steering				
	Brakes		Modification				
	General						
3. Conditions of Tyres							
		Size	Make		Balance		
	R/H Front Tyre				mm		
	L/H Front Tyre				mm		
	R/H Rear Tyre				mm		
	L/H Rear Tyre				mm		
١.		Description	on of Damages				
5.	General Information						
	Accident Date	26/04/2022	Inspection Dat	е	27/04/2022		
	Survey held at	FUNMASTERS PROMOTION					
		BLK 176, SIN MING DRIVE #03-21 SIN MING AUTOCARE SINGAPORE 575721					
5a.		Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.						